

500 Consumers Road
North York, Ontario M2J 1P8
PO Box 650
Scarborough ON M1K 5E3

Stephanie Allman
Regulatory Coordinator
Telephone: (416) 495-5499
Fax: (416) 495-6072
Email: EGDRRegulatoryProceedings@enbridge.com



October 20, 2014

VIA COURIER AND EMAIL

Ms. Kirsten Walli
Board Secretary
Ontario Energy Board
2300 Yonge Street, Suite 2700
Toronto, ON M4P 1E4

Re: Enbridge Gas Distribution Inc. ("Enbridge")
EB-2012-0013 - Angus Reinforcement Pipeline Project
Conditions of Approval – Addendum to Final Monitoring Report

Further to the Final Monitoring Report for the Angus Reinforcement Pipeline project filed with the Ontario Energy Board on May 27 2014, please find enclosed an Addendum to the Final Monitoring Report.

In the Final Monitoring Report, some areas were identified to require additional restoration. This addendum reports on the results of the additional restoration efforts.

If you have any questions, please contact the undersigned.

Yours truly,

(Original Signed)

Stephanie Allman
Regulatory Coordinator

cc: Zora Crnojacki, OPCC Chair
Pascale Duguay, Manager, Facilities Applications, Ontario Energy Board (via courier and email)

Table of Contents

Description

1.0 Introduction	Page 1
2.0 Residual Issues	Page 1
3.0 Summary	Page 2

Appendices

APPENDIX A: PIPELINE ROUTE MAP	Page 3
Figure 1: Map of Angus Reinforcement Pipeline Project	Page 4
APPENDIX B: PHOTO LOG (October 7, 2014)	Page 5

**ENBRIDGE GAS DISTRIBUTION INC.
POST-CONSTRUCTION
ENVIRONMENTAL MONITORING REPORT NO.2
ANGUS REINFORCEMENT PIPELINE PROJECT
EB-2012-0013**

Prepared by
Enbridge Gas Distribution Inc.
October 8, 2014

1.0 Introduction

In June of 2012 the Ontario Energy Board (“OEB”) under docket number EB-2012-0013 granted Enbridge Gas Distribution Inc. (“Enbridge”) Leave to Construct and operate an nominal pipe size (NPS) 6 (6-inch outer diameter) natural gas pipeline to reinforce the existing natural gas distribution network in Angus and surrounding communities.

Construction of the Angus Reinforcement Pipeline Project began on October 26, 2012 and was completed and energized on February 20, 2013.

Interim and final post-construction environmental monitoring reports have been filed with the OEB on August 19 2013 and May 27 2014 respectively. In the May 2014 report, some areas were identified to require additional restoration. Restoration activities included application of topsoil, seed and/or erosion control matting to ensure further vegetative growth and to reduce erosion. This additional restoration was completed by the end of September, 2014. This letter serves an addendum to the final monitoring report demonstrating that no further restoration is required.

2.0 Residual Issues

Vegetation has reestablished along the road allowances in all of the areas mentioned in the final monitoring report where it was disturbed due to construction.

Erosion, evidenced by rills and gullies in the bank and ditch of the road allowance occurred along several sections of the north side of County Road 21 (refer to locations in the final monitoring report). All areas of erosion have been addressed and vegetation has reestablished.

Erosion control devices such as silt fences and straw bales were installed where required to control any erosion and sedimentation. All such devices have been removed.

The bank approximately 50 meters east of 5162 County Road 21 was incorrectly identified as being impacted due to Enbridge's construction activities, so remediation was not conducted in this area as indicated in the interim and final post-construction environmental monitoring reports (see Photo 6 in Appendix B).

3.0 Summary

This letter serves as an addendum to the final monitoring report demonstrating that no further restoration is required. Measures implemented during construction and clean-up have been successful.

APPENDIX A
PIPELINE ROUTE MAP




Figure 1: Angus Reinforcement Pipeline Project

APPENDIX B
PHOTO LOG
(October 7, 2014)



Photo 1: Looking west of 4940 County Road 21



Photo 2: Looking east towards 4992 County Road 21



Photo 3: Looking west of 4992 County Road 21



Photo 4: Looking west on north side of County Road 21 in vicinity of 5057 County Road 21



Photo 5: Looking west on north side of County Road 21 in vicinity of 5057 County Road 21



Photo 6: Approximately 50 meters east of 5162 County Road 21



Photo 7: Looking west towards 5162 County Road 21



Photo 8: Looking west on north side of County Road 21 in vicinity of 5327 County Road 21



Photo 9: Looking east on north side of County Road 21 in vicinity of 5327 County Road 21



Photo 10: Looking west on south side of Innisfil Beach Road in vicinity of 4118 Innisfil Beach Road