

McCarthy Tétrault LLP  
PO Box 48, Suite 5300  
Toronto-Dominion Bank Tower  
Toronto ON M5K 1E6  
Canada  
Tel: 416-362-1812  
Fax: 416-868-0673

**Gordon M. Nettleton**  
Partner  
Email: gnettleton@mccarthy.ca

**mccarthy  
tétrault**

**December 8, 2016**

**VIA RESS AND COURIER**

Kirsten Walli  
Board Secretary  
Ontario Energy Board  
P.O. Box 2319  
2300 Yonge Street, 27th Floor  
Toronto, Ontario M4P 1E4

Dear Ms. Walli:


**RE: EB-2016-0160 Hydro One Networks Inc. ("Hydro One") Transmission Rates  
Application – Responses to Undertakings J7.02 and J7.03**

Hydro One's responses to Undertakings J7.02 and J7.03 are enclosed.

Yours truly,

**McCarthy Tétrault LLP**  
Per:



 Gordon M. Nettleton  
GMN

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16

**UNDERTAKING – J7.2**

**Undertaking**

To provide the numbers for the general replacement of breakers, the number that you are replacing that are in high or very high risk.

**Response**

The requested numbers are provided below.

Total Breaker Replacements in Test Years	198
Breakers that are High Risk	9
Breakers that are Very High Risk	3

The numbers provided in the table above refer to the number of circuit breakers at high risk and very high risk based on asset condition. The majority of the proposed breaker replacements over the test years are due to obsolescence, safety and poor performance issues, as described in Exhibit B1, Tab 2, Schedule 6, pages 9-18, of the application.

**UNDERTAKING – J7.3**

1  
2  
3  
4  
5  
6  
7  
8  
9

**Undertaking**

Provide the number of the 66 or 132 that are in high risk or very high risk condition.

**Response**

Please see Exhibit J7.2.