

Hearst Power Distribution Company Limited

System Assessment Survey

Date: 12 April 2010 Performed by: _____

Page No.: 7

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed					Comments		
		P	PL	TX	I	SS			2010	2011	2012	2013	2014		2015	
1104	Cecile Trailer Parc	X					O.K									
1105	Cecile Trailer Parc	X					O.K									
1106	Cecile Trailer Parc	X					O.K									
1107	Cecile Trailer Parc	X					O.K									
1108	Cecile Trailer Parc	X					O.K									
1109	Cecile Trailer Parc	X					O.K									
1110	Cecile Trailer Parc	X		X			O.K									
1111	Cecile Trailer Parc	X					O.K									
1112	Cecile Trailer Parc	X					O.K									
1113	Cecile Trailer Parc	X					O.K									
1114	Cecile Trailer Parc	X					O.K									
1114.5	Cecile Trailer Parc	X					O.K									
1117	Cecile Trailer Parc	X					O.K									Campground
1118	Cecile Trailer Parc	X					O.K									Campground
1130	206 Hwy 11 E.	X					O.K									
1131	208 Hwy 11 E.	X					O.K									
1132	210 Hwy 11 E	X					O.K									
1132.5	212 Hwy 11 E	X					O.K									
1133	214 Hwy 11 E	X					O.K									
1134	222 Hwy 11 E	X					O.K									
1004	Hwy 11 E	X					O.K									Street Light Pole
1004.5	Hwy 11 E	X					O.K									Jack Repair
1005	Hwy 11 E	X		X			O.K									Jack Repair. TX RUSTY

Hearst Power Distribution Company Limited
System Assessment Survey

Date: 19 April 200 Performed by: _____

Page No.: 15

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed						Comments	
		P	PL	TX	I	SS			2010	2011	2012	2013	2014	2015		
686	583 S.	X				X	O.K									Stub Pole
687	583 S.	X	X			X	O.K									
688	583 S.	X	X				Damage Surface	MH								
688.5	583 S.	X				X	O.K									not Tagged
689	583 S.	X	X	X	X	X	O.K									
689.5	583 S.	X				X	O.K									street Light
690	? Cemetery Rd.	X	X	X	X	X	O.K									
697		X	X				O.K									
698	Girard Farm	X	X			X	O.K									
699	Girard Farm	X	X	X	X	X	O.K									TX RUSTY
699.1	Girard Farm	X				X	old Cedar Pole	M								
692	Girard Farm	X														Street Light
695	258 Girard Rd.	X	X	X	X	X	O.K									
696	Girard Rd.	X					1/4 pvc pipe need support									street Light Pole
691	Girard Rd.	X				X	O.K									Stub Pole
? 270	(583 S.)	X	X	X	X	X	Transformer Rusted	M								
? 270	583 S.	X	X			X	O.K									
? 275	583 S.	X				X	O.K									
? 279	583 S.	X				X	O.K									
? 289	583 S.	X				X	O.K									Stub pole
? 293	583 S.	X				X	O.K									Stub pole
? 295	583 S.	X				X	O.K									Stub pole
? 299	583 S.	X		X		X	O.K									Stub pole TX RUSTY

Hearst Power Distribution Company Limited
System Assessment Survey

Date: 21 April 2010 Performed by: _____

Page No.: 127
25

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed					Comments	
		P	PL	TX	I	SS			2010	2011	2012	2013	2014		2015
	Bell Mobilite line	X	X		X		OK								
1467	1917 Hwy. 11 W.	X				X	OK								Street Light Pole
AXGDVV	Morin RD. ^{of Gate} East Side	X	X		X		O.K								
AXGDVA	Morin RD.	X	X		X		O.K								
AXGDWF	Morin RD.	X	X		X		O.K								
AXGDXX	Morin RD.	X	X		X		O.K								
AXGDYP	Morin RD.	X	X		X		OK Two wholes in it	L							
	Morin RD.	X	X		X		O.K								
	Morin RD.	X	X		X		O.K								
	Morin RD.	X	X		X		O.K								
	Morin RD.	X	X		X		O.K								
	Morin RD.	X	X	X	X	X	O.K								
	Geater Morin House	X				X	O.K								Stub Pole
	54 Morin RD.	X	X	X	X	X	O.K								
	Morin Camping Ground	X	X		X	X	O.K								
	Morin Camping Ground	X	X	X	X	X	O.K								
	57 Morin RD.	X				X	O.K								Stub Pole
	Serge Pominville	X				X	O.K								Stub Pole
	Hwy 11 W	X				X	O.K								Stub Pole
	1884 Hwy 11 W	X	X	X	X	X	O.K								
1476	1876 Hwy 11 W	X				X	O.K								Stub Pole
1475	1864 Hwy 11 W	X				X	O.K								Stub Pole (Pole leaning)

Hearst Power Distribution Company Limited
System Assessment Survey

Date: Apr. 13, 2010

Performed by: MARC

Page No.: 1

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed						Comments	
		P	PL	TX	I	SS			2010	2011	2012	2013	2014	2015		
656	512 Boullay.	✓	✓	✓			OK.	L								
657	520 Boullay.	✓	✓				OK	L								
658	528 Boullay	✓	✓		✓	✓	Pole OK.	L								Brown dead-end bell + insulator
659	Corner 6th + Boullay	✓	✓			✓	OK	L								
660	605 Boullay.	✓	✓	✓		✓	OK.	L			✓					Tx rusted.
661	609 Boullay	✓	✓			✓	OK	L								
662	617 Boullay.	✓	✓	✓		✓	OK	L								
663	620 Boullay.	✓	✓			✓	Crack all length of pole.	L							✓+	Monitor condition.
639	79 7th	✓	✓		✓	✓	OK.	L								Tighten guy wires, brown dead-end bell
640	75 7th.	✓	✓	✓		✓	OK	L								
641	69 7th.	✓	✓			✓	OK	L								
	72 7th.	✓				✓	OK.	L								Secondary road crossing.
642	Corner 7th + Boullay	✓	✓		✓	✓	OK	L								Brown dead-end bell.
643	63 7th.	✓	✓			✓	Minor damage at ground like	L								Monitor condition
644	59 7th.	✓	✓	✓		✓	OK	L								Tx rusted.
	64 7th.	✓				✓	OK new pole.	L								installed 2009
	58 7th.	✓				✓	OK new pole.	L								installed 2008
630	57 8th St.	✓	✓			✓	OK.	L								
624	Villa Beau-Seigneur ^{8th St.} Garage	✓				✓	OK.	L								Secondary road crossing.
	63 8th St.	✓	✓			✓	Burnt hole 6' from top	L							✓+	Monitor condition.
	67 8th St.	✓	✓	✓		✓	OK.	L								
627	73 8th St.	✓	✓			✓	OK	L								
626	79 8th St.	✓	✓		✓	✓	Pole OK.	L								Brown dead-end bells.

Hearst Power Distribution Company Limited

System Assessment Survey

Date: Apr. 13, 2010 Performed by: Mauc

Page No.: 2

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed					Comments	
		P	PL	TX	I	SS			2010	2011	2012	2013	2014		2015
625	80 8th St.	✓				✓	Rotted at ground line	VH	✓						Broken strain insulator.
	Conseil des Arts (East)	✓				✓	OK.	L							Pole in east side parking lot.
	Corner 9th + Kitchener (SE)	✓	✓				OK.	L							Single lip insulators (grey)
621	817 Kitchener.	✓	✓			✓	OK.	L							YR 2002
622	815 Kitchener.	✓	✓	✓		✓	OK.	L							YR 2002
	810 Kitchener (yard)	✓				✓	OK	L							triplex rubbing against eave
623	805 Kitchener.	✓	✓	✓		✓	OK	L							YR 2002
631	Corner 8th + Kitchener (SE)	✓	✓			✓	OK	L							
	Corner 8th + Kitchener (NE)	✓				✓	OK.	L							Road crossing + guy pole.
633	709 Kitchener.	✓	✓	✓		✓	OK	L							
634	707 Kitchener.	✓	✓			✓	OK	L							YR 1987
645	Kitchener + 7th (SE)	✓	✓		✓	✓	Pole OK.	L							Brown dead-end bell.
	Kitchener + 7th (NE)	✓				✓	OK.	L							Guy pole.
646	625 Kitchener.	✓	✓			✓	OK.	L							YR 1966
647	611 Kitchener	✓	✓	✓		✓	OK	L							
648	603 Kitchener	✓	✓			✓	OK	L							YR 2002
649	Kitchener + 6th (SW)	✓	✓			✓	OK	L							
	Kitchener + 6th (SE)	✓	✓			✓	OK	L							YR 2005
652	523 Kitchener	✓	✓			✓	OK	L							Reset steel guard.
653	517 Kitchener	✓	✓	✓		✓	OK	L							YR 1971
654	505 Kitchener	✓	✓	✓		✓	minor damage near ground line	L							Monitor condition
434	5th St. (OCWA Booster)	✓	✓	✓		✓	minor moss on X-arm	L							YR 1968 - Monitor condition.
433	Kitchener + 5th (SW)	✓	✓			✓	OK.	L							Brown pin insulator.

KITCHENER DATA

MAUC

VERY OLD

Hearst Power Distribution Company Limited

System Assessment Survey

Date: Apr. 13, 2010 Performed by: Max

Page No.: 4

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed						Comments	
		P	PL	TX	I	SS			2010	2011	2012	2013	2014	2015		
214	923 Edward.	✓	✓	✓		✓	OK	L							✓+	
510	Edward (Town Hall ent.)	✓					minor damage near bottom	L							✓	guy pole.
215	⁹²³ Edward	✓	✓			✓	large gash near bottom	ML						✓		Monitor condition.
511	Edward (Town Hall park)	✓				✓	OK.	L							✓+	Parking lot plug in service
512	10th + Edward (NW)	✓	✓			✓	OK	L							✓+	High School primary dip.
219	10th + Edward (SW)	✓	✓	✓		✓	OK.	L							✓+	Town Hall + tincan 3/4 bank.
218	10th (St-Louis)	✓	✓	✓		✓	OK	L							✓+	
217	10th (St-Louis yard)	✓	✓			✓	OK	L							✓+	
216	10th (tincan @ river)	✓				✓	minor rot at ground like	ML						⊙		600V secondary.
	10th (school garage)	✓				✓	OK	L							✓+	
220	St-Louis Edward	✓	✓			✓	OK	L							✓+	Acena primary dip pole.
221	St-Louis Edward	✓	✓			✓	Minor damage at bot.	L							✓+	monitor condition.
	St-Louis Edward.	✓	✓	✓		✓	OK.	L							✓+	
223	Edward St-Louis (west)	✓	✓	✓		✓	Cedar pole - rough shape	ML						⊙		monitor condition.
	1100 Edward (Daycare)	✓				✓	OK new pole	L							✓+	YR 2006
230	1100 Edward.	✓	✓			✓	Cedar pole.	L							✓+	monitor condition
231	1114 Edward.	✓	✓	✓		✓	OK.	L							✓+	
232	1124 Edward.	✓	✓			✓	Cedar pole	ML						⊙		monitor condition.
233	12th + Edward (NW)	✓	✓			✓	Cedar pole	L							✓+	
224	12th + Edward (SW)	✓					OK	L							✓+	guy pole.
234	1206 Edward.	✓	✓			✓	Cedar pole	L							✓+	monitor condition
235	1224 Edward	✓	✓	✓		✓	Cedar pole	L							✓+	YR. 1968 - monitor condition ^{Trusty}
236	13th + Edward. (NW)	✓	✓			✓	New pole OK.	L							✓+	YR 2002

Hearst Power Distribution Company Limited
System Assessment Survey

Date: Apr. 14, 2010 Performed by: Marc

Page No.: 6

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed					Comments	
		P	PL	TX	I	SS			2010	2011	2012	2013	2014		2015
399	1322 Alex.	✓	✓	✓		✓	OK.	L						✓+	YR. 1966
398	1312 Alex.	✓	✓	✓		✓	OK	L						✓+	
397	1308 Alex.	✓	✓			✓	OK	L						✓+	
396	13th + Alex (NW)	✓	✓			✓	OK.	L						✓+	
395	1224 Alex.	✓	✓	✓		✓	Minor damage near bottom	L						✓+	moulding broken.
394	1216 Alex.	✓	✓			✓	OK.	L						✓+	
393	1210 Alex.	✓	✓	✓		✓	OK.	L						✓+	YR. 1965 TX RUSTY
392	1204 Alex.	✓	✓	✓		✓	Minor surface peeling.	ML					✓		Monitor condition 1/2 1963
391	12th + Alex. (NE)	✓	✓			✓	OK.	L						✓+	
390	1122 Alex.	✓	✓			✓	OK	L						✓+	
	1123 Alex.	✓				✓	OK.	L						✓+	Secondary pole.
389	1116 Alex.	✓	✓			✓	OK	L						✓+	YR. 1988
388	1108 Alex.	✓	✓	✓		✓	OK	L						✓+	
387	1100 Alex. (Tennis)	✓				✓	OK	L						✓+	Secondary pole.
505	912 Alex.	✓	✓	✓		✓	OK. - leaning east.	L						✓+	CBPS 3ø bank.
506	CBPS Parking.	✓				✓	OK.	L						✓+	
504	906 Alex.	✓	✓	✓		✓	OK - leaning east.	L						✓+	
460	826 Alex.	✓	✓			✓	OK.	L						✓+	YR. 1998
459	816 Alex.	✓	✓	✓		✓	Minor damage 10' up pole	L						✓+	Monitor condition.
458	810 Alex.	✓	✓	✓		✓	OK.	L						✓+	YR. 1988
457	800 Alex.	✓	✓			✓	OK.	L						✓+	YR. 1988
452	8th + Alex.	✓	✓	✓		✓	OK - top leaning east.	L						✓+	ground rod to be reset.
455	27 8th St.	✓				✓	Minor dam. near bottom	L						✓	monitor condition

Hearst Power Distribution Company Limited

System Assessment Survey

Date: Apr. 14, 2010 Performed by: Max.

Page No.: 8

Abbreviations: VH Very High H High MH Medium-High M Medium ML Medium-Low L Low
 P Pole PL Primary Lines TX Transformers I Insulators SS Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed					Comments	
		P	PL	TX	I	SS			2010	2011	2012	2013	2014		2015
189	5th + Prince	✓	✓			✓	OK.	L						✓+	
190	504 Prince	✓	✓			✓	OK.	L						✓+	
191	512 Prince.	✓	✓	✓		✓	OK.	L						✓+	ground moulding to repair.
192	518 Prince.	✓	✓			✓	OK	L						✓+	
193	628 Prince.	✓	✓			✓	OK	L						✓+	
475	608 Prince	✓	✓			✓	OK	L						✓+	
476	618 Prince.	✓	✓	✓		✓	OK.	L						✓+	YR. 1965 Class 6
477	622 Prince.	✓	✓			✓	OK.	L						✓+	YR. 1967
478	7th + Prince (NE)	✓	✓			✓	OK	L						✓+	
479	7th + Prince (NW)	✓	✓			✓	OK.	L						✓+	LS-M3-2B.
480	706 Prince.	✓	✓	✓		✓	5' set depth.	L						✓+	Monitor condition.
481	716 Prince	✓	✓			✓	OK.	L						✓+	YR 1965 Class 6.
482	724 Prince	✓	✓			✓	OK.	L						✓+	YR. 1965 Class 6.
	8th + Prince .	✓	✓			✓	OK.	L						✓+	YR 2003
484	800 Prince.	✓	✓			✓	OK	L						✓+	
485	808 Prince.	✓	✓			✓	OK.	L						✓+	YR. 2002
486	812 Prince	✓	✓	✓		✓	Minor damage at bottom	L						✓	Monitor condition
487	824 Prince.	✓	✓			✓	OK.	L						✓+	
488	9th + Prince. (NE)	✓	✓			✓	Cracks in pole.	L						✓+	Monitor condition
489	818B Prince	✓				✓	OK.	L						✓+	Secondary pole.
490	818-B Prince.	✓				✓	OK.	L						✓+	Secondary pole.
491	824 Prince .	✓				✓	3 large notches cut in pole	L						✓	Monitor condition - Secondary only.
492	Municipal parking.	✓				✓	OK.	L						✓+	Street light pole.

Hearst Power Distribution Company Limited

System Assessment Survey

Date: Apr. 15, 2010 Performed by: Mace

Page No.: 9

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed					Comments	
		P	PL	TX	I	SS			2010	2011	2012	2013	2014		2015
493	Municipal Parking.	✓				✓	OK.	L						✓+	Street light pole
494	Municipal Parking	✓				✓	Large cracks, gouge near bot.	L						✓	Monitor condition - Street light.
587	908 Prince. (Caisse)	✓	✓	✓		✓	Pole ok. - leaning to road.	L						✓+	Y.R. 1988
588	914 Prince	✓	✓	✓		✓	Pole ok - Set depth about 4'	M				⊙			Y.R. 1965 Class 5 - check depth
589	924 Prince	✓	✓	✓		✓	Pole ok.	L						✓+	Y.R. 1967 Cl. 5
589-1	10th + Prince.	✓	✓			✓	OK.	L						✓+	
592	16 10th St.	✓				✓	minor damage near bot.	L						✓+	Monitor condition - See. only
593	14 10th St.	✓				✓	minor damage near bot.	L						✓+	Monitor condition - See. only.
594	11 10th St.	✓				✓	minor damage near bot.	M				⊙			Set depth about 3 1/2'.
595	15 10th St.	✓				✓	minor damage near bot.	L						✓+	Monitor cond.
590	1006 Prince.	✓	✓			✓	Cedar pole. - rough shape	VH	⊙ ok						Top of pole is a hazard.
591	1018 Prince.	✓	✓	✓		✓	OK.	L						✓+	
596	1024 Prince.	✓	✓			✓	Minor damage near bot.	L						✓+	Monitor condition.
598	11th + Prince.	✓	✓			✓	OK.	L						✓+	
597	13 11th. St.	✓				✓	OK.	L						✓+	Sec. only.
599	1108 Prince	✓	✓	✓		✓	OK.	L						✓+	
600	1116 Prince.	✓	✓			✓	Minor damage to bot.	L						✓+	Monitor cond.
601	1124 Prince.	✓	✓	✓		✓	OK - leaning east.	L						✓+	
602	1208 Prince.	✓	✓	⊘		✓	Pole ok.	L						✓+	Y.R. 1988 → Pole top pin - tighten
603	1222 Prince.	✓	✓	✓		✓	Large cracks	L						✓+	Monitor cond.
604	1224 Prince.	✓	✓			✓	Stamp at 5 1/2"	MH				⊙			No set deep enough Y.R. 1965 Cl.
605	1300 Prince.	✓	✓			✓	Minor damage to bot.	L						✓+	Monitor cond. Y.R. 1965 Cl. 5
	1300 Prince	✓				✓	3 notches cut in pole.	L						✓+	Monitor condition

Hearst Power Distribution Company Limited

System Assessment Survey

Date: Apr. 15, 2010 Performed by: Mauc.

Page No.: 10

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed					Comments	
		P	PL	TX	I	SS			2010	2011	2012	2013	2014		2015
607	1310 Prince.	✓	✓	✓		✓	OK.	L						✓+	YR. 1991
608	1314 Prince.	✓	✓	✓		✓	Minor dam. to bot.	L						✓+	Monitor cond. YR. 1965 CLS
609	1324 Prince.	✓	✓			✓	Pole Hollow at ground line	UH.	✓OK →						leaning a lot towards roads.
610	1400 Prince.	✓	✓			✓	OK.	L						✓+	
611	1404 Prince.	✓	✓	✓		✓	Hollow at ground line	UH.	✓OK						
612	1412 Prince.	✓	✓			✓	OK.	L						✓+	
613	1420 Prince.	✓	✓			✓	OK.	L						✓+	YR. 1972 CL4 - leaning east.
614	1428 Prince.	✓	✓	✓		✓	OK.	L						✓+	YR 1985 CL4-46'
615	1436 Prince.	✓	✓			✓	OK.	L						✓+	YR. 1987 CL3 35'
616	1440 Prince.	✓				✓	Med. cracks, - leaning east	L						✓+	Monitor cond. - see + guy pole.
618	15th + Prince (NW)	✓				✓	OK.	L						✓+	
281	15th + Front. (SE)	✓	✓	✓		✓	OK	L						✓+	Joint use with H1
282	1435 Front.	✓	✓	✓		✓	OK.	L						✓+	3" PVC Pipe broken.
283	1425 Front	✓	✓	✓		✓	OK.	L						✓+	YR. 1991 40-4
284	1425 Front	✓	✓		✓	✓	OK.	L						✓+	Moss on X-arm - single lip ins.
379	1416 Front	✓				✓	OK	L						✓+	See. only.
380	1420 Front	✓				✓	OK.	L						✓+	Sec. only.
285	1413 Front	✓	✓	✓	✓	✓	Pole OK - single lip ins	L						✓+	moss on X-arm.
286	1405 Front	✓	✓	✓	✓	✓	Pole OK. - moss on Xarm	L						✓+	Evaluate cond. of 3rd ^{TX} rack
287	1405 Front	✓	✓		✓	✓	Cracks in pole - single lip ins.	L						✓+	Monitor condition.
288	Tim Hortons	✓	✓		✓	✓	Pole OK.	L						✓+	Single lip insulators
289	Tim Hortons	✓	✓	✓		✓	OK.	L						✓+	Pole crib damaged.
290	The Bargain Shop.	✓	✓			✓	OK.	L						✓+	YR 2007 45-4 IBS 07-00640

Hearst Power Distribution Company Limited

System Assessment Survey

Date: Apr. 15, 2010 Performed by: Mare

Page No.: 11

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
 P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed					Comments	
		P	PL	TX	I	SS			2010	2011	2012	2013	2014		2015
291	Sam's Car Sales.	✓	✓	✓		✓	OK - new pole.	L						✓+	YR 2007 45-4
	Sam's Car Sales.	✓	✓	✓		✓	OK - new pole.	L						✓+	YR 2008 50-3 LBS-08-0556
295	1221 FRONT	✓	✓	✓		✓	OK new pole.	L						✓+	YR 2007 45-4
294	1221 FRONT	✓				✓	OK.	L						✓+	See only.
293	1221 FRONT	✓				✓	OK	L						✓+	See only.
296	1211 FRONT.	✓	✓			✓	OK, new pole	L						✓+	YR 2006 45-4
297	1211 FRONT	✓	✓	✓		✓	OK.	L						✓+	YR 1993 40-4 - check ground.
298	12th + FRONT (NW)	✓	✓	✓		✓	Minor burn damage at sw.	L						✓+	YR 1996 -45-4 - Monitor cond.
299	1131 FRONT	✓	✓			✓	Minor damage near bot.	L						✓+	YR 1972 40-4 - Monitor cond.
300	1129 FRONT	✓	✓			✓	Minor damage near bot	L						✓+	YR 1989 40-3 - Monitor cond.
301	old Petro-Can station	✓	✓	✓		✓	OK.	L						✓+	
302	Cézar Bowling.	✓	✓	✓		✓	OK	L						✓+	YR 1971 40-4 minor tx leak
303	11th + FRONT.	✓	✓		✓	✓	Pole OK.	L						✓+	Brown bells.
304	Hearst Supermarket.	✓	✓	✓		✓	OK.	L						✓+	YR 1988 45-4
305	1015 FRONT	✓	✓	✓		✓	minor dam. near bot.	L						✓+	Monitor condition. - ground rod.
306	1007 FRONT.	✓	✓			✓	OK. - leaning	L						✓+	YR 1969 40-6
307	10th + FRONT. (SW)	✓	✓	✓	✓	✓	minor dam. near bot. - 6' Xarm	L						✓	Single lip insulators.
343	10th + FRONT (NE)	✓	✓			✓	minor dam. 8' from bot.	L						✓+	Monitor condition.
308	923 FRONT	✓	✓			✓	minor dam. near bot.	L						✓+	Monitor condition.
309	923 FRONT	✓	✓			✓	OK.	L						✓+	YR 1991 45-3
310	911 FRONT	✓	✓	✓		✓	minor dam. near bot.	L						✓+	Monitor cond.
311	907 FRONT	✓	✓			✓	OK.	L						✓+	
338	904 FRONT.	✓	✓				OK.	L						✓+	

Hearst Power Distribution Company Limited

System Assessment Survey

Date: Apr. 15, 2010 Performed by: Marc.

Page No.: 12

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed						Comments	
		P	PL	TX	I	SS			2010	2011	2012	2013	2014	2015		
	904 FRONT (back)	✓	✓	✓		✓	OK.	L							✓+	
	GRANDIN Garage.	✓				✓	OK.	L							✓+	See only.
	908 FRONT (old shell)	✓				✓	OK.	L							✓+	See. only.
337	900 FRONT.	✓				✓	OK.	L							✓+	See. + guy pole.
312	9th + FRONT (SW)	✓	✓			✓	OK.	L							✓+	✓R 1973 45-5
313	9th + FRONT (SE)	✓	✓	✓		✓	Med damage to pole	ML							✓	Monitor condition.
314	823 FRONT.	✓	✓			✓	Minor dam. to bot.	L							✓	Monitor condition.
335	822 FRONT.	✓				✓	OK.	L							✓+	
315	817 FRONT	✓	✓	✓	✓	✓	Pole OK.	L							✓+	Single lip insulators.
316	807 FRONT	✓	✓	✓	✓	✓	Pole OK. - 6' X-arm	ML							✓	Single lip insulators.
317	Northern (FRONT)	✓	✓	✓	✓	✓	minor dam. @ bot.	L							✓+	✓R 1963 40-5
318	8th + FRONT.	✓	✓		✓	✓	6' X-arm - single lip ins.	L							✓	✓R 1969 40-5
333	800 FRONT	✓				✓	OK.	L							✓+	✓R 1987 35-3
332	800 FRONT (Back)	✓				✓	OK.	L							✓+	✓R 1965 35-6
319	Hearst lumber Wash.	✓	✓			✓	OK.	L							✓+	✓R 1985 45-4
320	Hearst lumber Wash	✓	✓	✓		✓	OK	L							✓+	✓R. 1985 45-4
321	715 FRONT.	✓	✓		✓	✓	Minor dam. @ bottom	L							✓+	Monitor condition - 6' X-arm.
322	707 FRONT	✓	✓		✓	✓	minor dam @ bot.	L							✓+	monitor cond. - 6' X arm.
323	701 FRONT	✓	✓	✓	✓	✓	minor dam @ 5' fr. bot.	L							✓+	monitor cond. - brown bells.
324	7th + FRONT (NW)	✓				✓	Cedar pole - rough.	M			(✓)					6000 see.

Hearst Power Distribution Company Limited

System Assessment Survey

Date: Apr. 16, 2010 Performed by: Mauc

Page No.: 13
14

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed					Comments		
		P	PL	TX	I	SS			2010	2011	2012	2013	2014		2015	
348	Tembee	✓	✓	✓			OK.	L							✓+	
347	Tembee	✓	✓				OK. - LBS for crane.	L							✓+	
346	Tembee	✓	✓				} ALL OK.	} L							} ✓+	} Support structure for log crane tx.
345	Tembee	✓	✓													
344	Tembee	✓	✓													
	Tembee mill LBS	✓	✓				OK	L							✓+	1/R. 2005 40-4
	Tembee mill (corner)	✓	✓				OK	L							✓+	1/R 2000 45-4
80	Tembee dry kiln	✓	✓	✓			OK	L							✓+	1/p. 1973 40
79	" " "	✓	✓	✓			OK - LBS	L							✓+	1/R 1973 40-3
78	Tembee planning mill	✓	✓				OK.	L							✓+	
77	" " "	✓	✓				OK.	L							✓+	
76	Tembee Planning LBS	✓	✓				OK - LBS.	L							✓+	1/R. 1994 45-4
75	Fontaine Dr.	✓	✓				OK.	L							✓+	40-4
74	Fontaine Dr.	✓	✓			✓	OK	L							✓+	
31-1	3RD + Front (N)	✓	✓				Cedar pole.	ML							✓	Monitor condition
175	3RD + Front (SW)	✓	✓			✓	Minor dam. near bottom	ML							✓	Monitor cond. - cedar pole.
176	3RD	✓	✓	✓	✓	✓	Cedar pole - wood pin X-arm	M								Replace X-arm.
177	3RD (Poulin 3rd bank)	✓	✓	✓		✓	OK.	L							✓+	
178	3RD (Columbia park)	✓	✓	✓		✓	OK.	L							✓+	1/R. 1972 40-5
179	3RD + Prince (NW)	✓	✓				OK.	L							✓+	1/R 1958 40-5
	3RD + Prince (NE)	✓					Pole OK.	L							✓+	1/R 1987 35-3
180	Columbia LBS	✓	✓				LS-CI-B - OK	L							✓+	
181	Columbia dead-end.	✓	✓				Minor dam near bottom	L							✓+	Monitor condition

Hearst Power Distribution Company Limited

System Assessment Survey

Date: Apr. 16, 2010. Performed by: Marc.

Page No.: 17

15

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed						Comments	
		P	PL	TX	I	SS			2010	2011	2012	2013	2014	2015		
	425 FRONT	✓				✓	OK.	L							✓+	See only.
556	5th + FRONT (SE)	✓				✓	OK	L							✓+	See only.
555	3 5th St.	✓				✓	OK	L							✓+	See only.
554	5 5th St.	✓				✓	OK	L							✓+	YR 2000 35-4
	5th + Prince.	✓	✓			✓	OK (Pole belongs to NTH)	L							✓+	
425	22 5th St.	✓	✓				OK.	L							✓+	YR. 1989 40-4
426	28 5th St.	✓	✓	✓		✓	OK	L							✓+	YR. 2002 40-4
427	5th + Alex. (NW)	✓	✓			✓	OK.	L							✓+	
428	5th + Alex (SW)	✓	✓			✓	OK	L							✓+	Cler-Uzan dip pole.
438	5th + Prince (NE)	✓				✓	OK	L							✓+	guy pole.
429	36 5th.	✓	✓	✓		✓	OK.	L							✓+	minor rust on tx.
437	35 5th.	✓				✓	OK.	L							✓+	See only.
430	38 5th	✓	✓			✓	OK.	L							✓+	moss on X-arm.
	5th + Edward (NW)	✓	✓			✓	OK.	L							✓+	YR 2007 40-4
	5th + Edward (SW)	✓	✓			✓	OK	L							✓+	YR 2007 45-4
436	5th + Edward (SE)	✓				✓	OK.	L							✓+	guy pole.
432	5th St.	✓	✓				OK.	L							✓+	Moss on X-arm - brown insulator.
433	5th + Kitchener (SW)	✓	✓			✓	OK	L							✓+	Brown insulators
435	5th + Kitchener (SE)	✓				✓	OK	L							✓+	Replace guy guards.
434	5th St (River)	✓	✓	✓		✓	Minor dam. near top	L							✓+	Monitor condition.
	CW tracks (behind label)	✓	✓				OK.	L							✓+	YR 2001 55-3
	Rotary Park.	✓	✓			✓	OK-	L							✓+	YR 2004 55-3
	6th + FRONT. (NW)	✓	✓			✓	OK.	L							✓+	YR 2004 50-3

Hearst Power Distribution Company Limited

System Assessment Survey

Date: Apr. 19, 2010 Performed by: Mauc.

Page No.: 15

16

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed					Comments	
		P	PL	TX	I	SS			2010	2011	2012	2013	2014		2015
464	6th + FRONT. (SW)	✓	✓			✓	OK.	L						✓+	HEPC 51
	6th + FRONT (SE)	✓	✓			✓	Cedar Pole.	M.			✓ ok →				OURS OR ONTARIO?
548	FRONT + HWY 11E (EASTVIEW AUTO)	✓	✓	✓	✓	✓	Pole ok.	L						✓+	BROWN bells.
465	6th + George. (NW)	✓	✓	✓		✓	OK.	L						✓+	
466	6th + George. (SW)	✓	✓		✓	✓	OK.	L						✓+	HEPC 51 - Brown dead-end bells
467	13 6th St.	✓	✓			✓	OK.	L						✓+	HEPC 51 - Remove unused triplex.
468	6th St. (Real fountain)	✓	✓	✓			Hollow at ground line	VH.	✓ → →						
469	6th. + Prince. (NW)	✓	✓		✓	✓	Pole OK.	L						✓+	Single lip insulators.
470	6th St. (Cassie)	✓	✓				OK.	L						✓+	HEPC 51 - minor moss on X-arm
471	6th St. (Beaulieu)	✓	✓			✓	OK.	L						✓+	HEPC 51 - minor moss on X-arm.
442	6th + Alex. (NW)	✓	✓			✓	OK.	L						✓+	HEPC 51
472	32 6th St.	✓	✓			✓	OK.	L						✓+	HEPC 51
473	38 6th St.	✓	✓	✓		✓	OK.	L						✓+	HEPC 51
474	6th + Edward.	✓	✓			✓	OK.	L						✓+	HEPC 51
650	50 6th St.	✓	✓	✓		✓	OK.	L						✓+	brown lightning arrester.
	6th + Kitchener (NW)	✓	✓			✓	Cedar pole.	VH.	✓						Rough shape.
635	48 7th.	✓				✓	OK.	L						✓+	See. only.
	46 7th.	✓				✓	OK.	L						✓+	YR. 2008 35-4
	12 7th.	✓				✓	OK.	L						✓+	HEPC 53
583	8th St. (Library)	✓	✓	✓		✓	Burnt hole near top.	M.						✓	Monitor condition. YR 89 40-3
454	35 8th.	✓				✓	OK.	L						✓+	See. only.
453	39 8th.	✓				✓	OK.	L						✓+	See. only.
	8th + Edward. (NE)	✓				✓	OK.	L						✓+	See. only.

Hearst Power Distribution Company Limited

System Assessment Survey

Date: Apr. 19, 2010 Performed by: Manc.

Page No.: 16

17

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed					Comments	
		P	PL	TX	I	SS			2010	2011	2012	2013	2014		2015
632	49 8th. St.	✓				✓	minor dam. near bot.	L						✓+	Monitor condition
519	9th St (south side r. Ver)	✓	✓	✓	✓	✓	Cedar pole.	ML					✓		minor damage at ground line.
517	68 9th. St.	✓	✓		✓	✓	minor gouge at bottom	L						✓+	Monitor condition - brown ins.
	64 9th St.	✓	✓	✓		✓	OK.	L						✓+	YR. 2007 45-4
515.	60 9th. St.	✓	✓			✓	Cedar Pole.	ML						✓	Monitor cond.
514	47 9th. St.	✓	✓	✓		✓	Cedar Pole.	ML							Burn damage near top.
513	45 9th St.	✓	✓			✓	large cracks.	ML						✓+	Monitor condition.
509	38 9th. St.	✓	✓	✓	✓	✓	Cracks in pole.	L						✓	Monitor cond. - single lip ins.
508	36 9th St.	✓	✓	✓	✓	✓	Pole OK.	L						✓+	6' X-am - single lip ins.
507	34 9th St.	✓	✓			✓	OK.	L						✓+	YR. 2003 40-4
	9th + Alex. (NW)	✓	✓			✓	OK.	L						✓+	YR 2007 45-4
502	26 9th. St.	✓	✓			✓	OK.	L						✓+	YR 90 40-4
501	9th St. (Caisse Parkway)	✓	✓	✓		✓	OK . Bad condition.	ML						✓+	
500	9th St. (Caisse Park)	✓	✓			✓	Cedar pole. - gouge @ bot.	M							Monitor condition.
499	9th + Prince. (NW)	✓	✓			✓	OK.	L						✓+	YR. 1972 40-4
498	16 9th. St.	✓	✓	✓		✓	OK.	L						✓+	YR. 2005 45-3
497	10 9th St.	✓	✓	✓		✓	OK.	L						✓+	YR. 2005 40-4
496	9th. + George.	✓	✓		✓	✓	OK.	L						✓+	Single lip ins.
495	9th St. - (Pharmacy)	✓	✓	✓		✓	OK.	L						✓+	
253	10 12th St.	✓	✓		✓	✓	OK.	L						✓+	single lip ins.
252	12 12th St.	✓	✓		✓	✓	OK.	L						✓+	YR. 1968 40-4 - single lip ins.
251	12th. + Prince (NW)	✓	✓		✓	✓	OK.	L						✓+	YR. 1968 - 40-4 - Single lip ins
250	12th + Prince (SW)	✓	✓			✓	OK.	L						✓+	YR 1993 - 40-3

Hearst Power Distribution Company Limited

System Assessment Survey

Date: Apr. 19, 2010 Performed by: M. G. C.

Page No.: 17

18

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed					Comments	
		P	PL	TX	I	SS			2010	2011	2012	2013	2014		2015
249	12th St.	✓	✓		✓	✓	Pole OK. - Brown ins.	L						✓+	Y.R. 1968 / 40-4
248	12th + Alex. (NW)	✓	✓		✓	✓	Pole OK. - Brown insul.	L						✓+	
247	12th St.	✓	✓		✓	✓	Pole OK. - Single dip insul.	L						✓+	40-5
520	9th. (South side river)	✓	✓			✓	Pole splited @ top.	VH.							
521	5835 + Halle.	✓	✓	✓	✓	✓	OK.	L						✓+	Y.R. 1976 Class 4
522	906 Halle.	✓	✓	✓		✓	OK.	L						✓+	
523	912 Halle.	✓	✓			✓	OK.	L						✓+	
524	916 Halle.	✓	✓	✓		✓	OK.	L						✓+	HEPC 63
525	916 Halle.	✓	✓			✓	OK.	L						✓+	TX OLD CRUSFY
526	920 Halle.	✓	✓		✓	✓	OK.	L						✓+	Brown dead-end bells
527	5835 (Begin)	✓	✓			✓	Minor damage @ bottom	L						✓+	Monitor condition
528	5835 + Piper. (NW)	✓	✓	✓	✓	✓	OK.	L						✓+	HEPC 75
532	5835 + Piper (SW)	✓	✓		✓	✓	Pole OK. - Brown insulators	L						✓+	Brown bells.
531	909 Piper.	✓	✓	✓		✓	Minor cracks in pole.	L						✓+	Monitor condition
530	917 Piper.	✓	✓			✓	OK.	L						✓+	HEPC 63
529	917 Piper.	✓				✓	OK.	L						✓+	guy + see pole. HEPC 77
533	116 Hwy 5835	✓	✓	✓		✓	OK.	L						✓+	
534	122 Hwy 5835	✓	✓		✓	✓	minor dam. at bottom	L						✓+	Monitor cond. - brown bells
535	902 Cessna	✓	✓			✓	OK.	L						✓+	#
536	904 Cessna.	✓	✓	✓		✓	OK.	L						✓+	HEPC 67
537	908 Cessna.	✓	✓		✓	✓	OK.	L						✓+	Brown bells.
538	909 Cessna	✓				✓	OK.	L						✓+	See. only.
	907 Cessna.	✓				✓	OK.	L						✓+	Y.R. 2000 35-4

Hearst Power Distribution Company Limited

System Assessment Survey

Date: Apr. 19, 2010 Performed by: Mare

Page No.: 18

19

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed					Comments		
		P	PL	TX	I	SS			2010	2011	2012	2013	2014		2015	
	903 Cessna.	✓				✓	minor damage near bottom	L							✓+	Monitor condition
540	583 S (Conrad Bağın)	✓	✓			✓	OK.	L							✓+	HEPC 53
541	130 Hwy 583S	✓	✓			✓	Crack in pole.	L							✓+	Monitor condition
542	136 Hwy 583S	✓	✓	✓		✓	OK.	L							✓+	HEPC 53 TX RUSTY
543	138 Hwy 583S	✓	✓			✓	OK.	L							✓+	
	Labelle + Hwy 11 W (Sw)	✓	✓				OK.	L							✓+	
701	Labelle (CPM propane)	✓	✓	✓		✓	OK.	L							✓+	YR. 1990 45-3
255	Labelle St. (Jean's)	✓	✓	✓		✓	OK - single lip ins.	L							✓+	
254	Labelle St. (Jean's)	✓	✓		✓	✓	Pole OK - brown bell	L							✓+	
702	Labelle St.	✓	✓	✓		✓	OK.	L							✓+	YR. 1990 45-3
703	End of Irwin.	✓	✓			✓	OK.	L							✓+	YR 1998 40-4
704	5 Irwin	✓	✓	✓		✓	OK.	L							✓+	YR. 1998 40-4
	Irwin + Labelle (sw)	✓	✓				OK.	L							✓+	YR. 1999 45-4
	Irwin + Labelle (SE)	✓					OK.	L							✓+	YR. 1999 35-4
705	18 Labelle.	✓	✓	✓		✓	OK.	L							✓+	YR 1990 45-3 - TX rusted.
	18 Labelle	✓	✓				OK.	L							✓+	YR 1999 45-4
706	22 Labelle	✓	✓	✓		✓	OK.	L							✓+	YR 1990 45-3
	28 Labelle	✓	✓				OK.	L							✓+	YR 1995 45-3
709	32 Labelle	✓	✓	✓		✓	OK.	L							✓+	
	34 Labelle.	✓	✓				OK.	L							✓+	YR. 1999 45-4
711	40 Labelle.	✓	✓	✓		✓	OK.	L							✓+	YR. 1990 45-3
713	48 Labelle.	✓	✓	✓		✓	minor moss on pole.	L							✓+	Monitor cond. HEPC 80
	48 Labelle	✓	✓			✓	OK.	L							✓+	YR. 1999 45-4

Hearst Power Distribution Company Limited

System Assessment Survey

Date: Apr. 17, 2010 Performed by: Marc

Page No.: 20
21

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed					Comments	
		P	PL	TX	I	SS			2010	2011	2012	2013	2014		2015
735	22 Bryant.	✓	✓	✓		✓	OK.	L						✓+	YR. 1990 45-3
736	30 Bryant.	✓	✓			✓	OK.	L						✓+	YR 1990 45-3
737	35 Bryant.	✓				✓	OK	L						✓+	See. only.
739	37 Bryant.	✓				✓	OK.	L						✓+	600 U See. - YR 1990 40-4
738	34 Bryant.	✓	✓	✓		✓	OK.	L						✓+	YR? 45-3
748	S Algoma.	✓	✓	✓	✓	✓	Pole OK - Brown ins.	L						✓+	TX RUSTY
749	Algoma + Bryant.	✓	✓				OK.	L						✓+	
756	Algoma + Wyborn.	✓	✓			✓	minor dam. near bottom	L						✓+	Monitor condition
757	Algoma	✓	✓		✓		Pole OK - Brown ins.	L						✓+	
758	Algoma (south dead-end)	✓	✓		✓		Pole OK - Brown bells	L						✓+	Replace guy guard.
759	ACR tracks line	✓	✓				OK - Single lip ins.	L						✓+	TRIM TREES
760	ACR tracks to pole.	✓	✓	✓		✓	OK.	L						✓+	
	ACR Track. (light).	✓				✓	OK.	L						✓+	
762	McNee (tracks)	✓	✓	✓		✓	OK	L						✓+	YR. 1990 45-3
761	McNee	✓	✓				OK.	L						✓+	
747	Algoma + McNee	✓	✓		✓	✓	Pole OK. - Brown bells	L						✓+	35-5
746	99 McNee	✓	✓			✓	Stamp at 6'	M							Reset. 35-7
745	91 McNee	✓	✓			✓	OK.	L						✓+	YR. 1991 35-7
744	85 McNee.	✓	✓	✓		✓	OK.	L						✓+	
743	85 McNee	✓	✓			✓	OK	L						✓+	YR? 35-7
742	71 McNee	✓	✓	✓		✓	OK.	L						✓+	YR 1991 40-4
741	69 McNee	✓	✓			✓	OK.	L						✓+	YR 1991 35-7
727	53 McNee	✓	✓	✓		✓	OK.	L						✓+	HEPC 71

ok →

Hearst Power Distribution Company Limited

System Assessment Survey

Date: Apr. 19, 2010 Performed by: Mace

Page No.: 21
22

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed					Comments	
		P	PL	TX	I	SS			2010	2011	2012	2013	2014		2015
726	49 McNee	✓	✓			✓	OK.	L						✓+	YR 1991 40-4
725	West + McNee.	✓	✓			✓	OK.	L						✓+	
724	McNee.	✓	✓			✓	OK.	L						✓+	
723	McNee.	✓	✓			✓	OK.	L						✓+	YR. 1995 40-4
722	McNee.	✓	✓			✓	OK.	L						✓+	YR. 1966 40-4
721	McNee	✓	✓			✓	OK.	L						✓+	YR. 1995 40-4
48	2 Fontaine DR.	✓	✓			✓	untreated pole - rough near top	ML						✓	Top bowed.
49	Fontaine + Hwy 11E	✓				✓	OK.	L						✓+	Triplex only.
50	ONR tracks (Hwy 11E)	✓				✓	OK.	L						✓+	Sec. only.
51	4 Fontaine DR.	✓	✓			✓	OK.	L						✓+	
52	6 Fontaine DR.	✓	✓	✓		✓	Minor surface dam.	L						✓	HEPC 59 - Monitor cond.
	Label Chalk Sew.	✓				✓	OK.	L						✓+	YR. 2006 35-4
53	8 Fontaine DR.	✓	✓			✓	OK.	L						✓+	HEPC 59
54	Fontaine + Tremblay	✓	✓			✓	OK.	L						✓+	Install neutral to 6th st line #50
55	Fontaine DR (west of Label)	✓	✓	✓		✓	OK.	L						✓+	YR? 45-4 - install neutral to #51
	618 Tremblay.	✓				✓	Minor surface dam.	L						✓+	Monitor cond. - See only. YR 51 ₃₅
	620 Tremblay.	✓				✓	OK.	L						✓+	HEPC 61
	622 Tremblay.	✓				✓	OK.	L						✓+	YR 1959 35-7
56	10 Fontaine.	✓	✓			✓	OK.	L						✓+	HEPC 61
58	12 Fontaine.	✓	✓			✓	OK.	L						✓+	YR. 1957 35-?
57	Fontaine + Tremblay	✓					OK.	L						✓+	Guy pole.
60	Fontaine + Rouse.	✓					OK.	L						✓+	Guy pole.
59	Fontaine + Rouse.	✓	✓	✓	✓	✓	Pole OK. - Wood-pil X-am	L						✓+	Brown insulators

Hearst Power Distribution Company Limited

System Assessment Survey

Date: Apr. 20, 2010 Performed by: Marc

Page No.: 22

23

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed					Comments	
		P	PL	TX	I	SS			2010	2011	2012	2013	2014		2015
61	16 Fontaine DR.	✓	✓			✓	OK.	L						✓+	YR. 1957 35-6
62	20 Fontaine. DR.	✓	✓			✓	OK.	L						✓+	YR. 1976 40-4
63	22 Fontaine. DR.	✓	✓			✓	Stamp @ 6'	L						✓+	YR? 35-6 Depth?
64	26 Fontaine DR.	✓	✓	✓		✓	OK.	L						✓+	YR. 1958 40-5
65	Villeneuve Cement	✓				✓	OK.	L						✓+	Sec. only.
66	Fontaine + Gannett	✓	✓			✓	OK.	L						✓+	YR 1996 40-4
67	34 Fontaine. DR.	✓	✓			✓	OK.	L						✓+	YR 1958 35-5
68	Fontaine + Allen.	✓	✓			✓	Wood Pin X-arm.	M							BROWN insulators.
69	Fontaine + Allen	✓					OK.	L						✓+	YR 1958 35-7 - guy pole
70	40 Fontaine DR.	✓	✓			✓	OK.	L						✓+	YR? 35-5
71	Fontaine. + Jolin.	✓	✓			✓	OK.	L						✓+	Single lip insulators
72	Fontaine + Jolin.	✓					OK.	L						✓+	Guy pole.
73	Fontaine DR.	✓	✓			✓	OK.	L						✓+	YR. ? 35-5
133	663 Jolin.	✓				✓	OK.	L						✓+	HEPC56 - Sec. only.
132	667 Jolin.	✓				✓	OK.	L						✓+	Sec. only.
131	667 Jolin.	✓	✓	✓	✓	✓	Pole OK. - Single lip ins.	L						✓+	
130	Jolin + Marchiblan.	✓	✓			✓	Pole OK - Single lip ins.	L						✓+	
129	Jolin.	✓	✓			✓	Pole OK - Single lip ins.	L						✓+	
	Longval Plug-in (Jolin ST)	✓				✓	OK.	L						✓+	YR. 2000 35-4 Sec. only
	Longval Plug-in (Jolin ST)	✓				✓	OK.	L						✓+	YR 1996 35-4 Sec. only.
128	644 Jolin.	✓	✓			✓	OK - Single lip ins.	L						✓+	
127	643 Jolin.	✓				✓	Cedar pole	ML						✓	Monitor condition
126	644 Jolin.	✓	✓	✓	✓	✓	Pole OK. - Single lip ins.	L						✓+	YR 197? 40-4

Hearst Power Distribution Company Limited

System Assessment Survey

Date: Apr. 20, 2010 Performed by: Marc

Page No.: 23
24

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
 P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed					Comments	
		P	PL	TX	I	SS			2010	2011	2012	2013	2014		2015
125	640 Jolin	✓	✓	✓	✓	✓	Pole OK - Single lap ins.	L						✓+	
	Jolin (behind ontrac)	✓				✓	OK.	L						✓+	3ø sec.
124	Jolin (behind ontrac)	✓				✓	OK.	L						✓+	See. only.
113	23 Rouse.	✓				✓	OK.	L						✓+	See. only.
114	25 Rouse.	✓				✓	OK.	L						✓+	See. only.
115	Rouse + Jolin	✓	✓			✓	OK.	L						✓+	YR 1968 40-4
116	29 Rouse.	✓	✓	✓	✓	✓	Pole OK - Single lap ins.	L						✓+	
117	33 Rouse	✓	✓		✓	✓	Pole OK - Single lap ins.	L						✓+	
118.	39 Rouse.	✓	✓	✓	✓	✓	Pole OK - Single lap ins.	L						✓+	Minor rust on txs
119	45 Rouse.	✓	✓	✓	✓	✓	Pole ok - single lap ins.	L						✓+	
120	End of Rouse.	✓	✓			✓	OK.	L						✓+	
121	42 Rouse.	✓				✓	OK.	L						✓+	YR. 195? 35-?
122	40 Rouse.	✓				✓	OK.	L						✓+	HEPC 75 600V sec.
123	34 Rouse.	✓				✓	OK.	L						✓+	See. only.
134	656 Allen st.	✓	✓	✓		✓	OK.	L						✓+	HEPC 59
135	Allen + Grannell.	✓	✓		✓	✓	Pole OK - Brown Bells + SW.	L						✓+	
136	645 Allen.	✓	✓			✓	OK.	L						✓+	YR. 1985 35-4
137	641 Allen.	✓	✓	✓		✓	OK.	L						✓+	YR 1956 40-5 - Broken 2" pipe
138	636 Allen.	✓	✓			✓	OK.	L						✓+	HEPC 59
108	Rouse + Allen.	✓	✓		✓	✓	OK - Brown bells	L						✓+	YR. 195? 35-6
109	631 Allen.	✓	✓			✓	OK.	L						✓+	
110	627 Allen.	✓	✓	✓		✓	OK.	L						✓+	YR 1958 40-5
111	623 Allen.	✓	✓			✓	OK.	L						✓+	YR. 195? 35-?

Hearst Power Distribution Company Limited

System Assessment Survey

Date: Apr 20, 2010 Performed by: Marc

Page No.: 27
29

Abbreviations: VH Very High H High MH Medium-High M Medium ML Medium-Low L Low
 P Pole PL Primary Lines TX Transformers I Insulators SS Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed					Comments			
		P	PL	TX	I	SS			2010	2011	2012	2013	2014		2015		
112	619 Allen.	✓	✓	✓	✓	✓	Blk OK - Brown bells	L							✓+	YR 1958 35-2	
	9 Rouse.	✓	✓			✓	OK.	L							✓+	YR. 2002 40-4	
106	9 Rouse	✓	✓	✓		✓	OK	L							✓+		
107	9 Rouse.	✓	✓			✓	OK.	L							✓+	See. only.	
105	5 Rouse.	✓	✓			✓	OK.	L							✓+	YR. 1958 35-5	
104	Rouse + Veilleux	✓	✓			✓	OK - Brown bells	L							✓+	YR 1958 35-6	
103	630 Veilleux.	✓	✓			✓	OK.	L							✓+	HEPC 59	
102	624 Veilleux	✓	✓	✓		✓	minor damage at bottom	L							✓+	Monitor cond. - Brown bells	
101	620 Veilleux.	✓				✓	OK.	L							✓+	See. only. HEPC 59	
150	625 Veilleux.	✓				✓	OK.	L							✓+	YR. 1978 35-5	
149	629 Veilleux.	✓				✓	cracks in pole.	L							✓+	Monitor condition	
148	631 Veilleux.	✓				✓	Stamp @ 6'	L							✓	Monitor depth. - YR. 1968 30-6	
147	Rouse + Veilleux	✓					OK.	L							✓+	guy pole. HEPC 59	
142	1 Rouse.	✓				✓	Cedar Pole.	ML							✓	See only.	
143	1 Rouse (alley)	✓				✓	OK.	L							✓+	YR 1967 30-6	
144	1 Rouse (alley)	✓				✓	OK.	L							✓+	YR ?	
145	1 Rouse (alley)	✓				✓	OK.	L							✓+	YR ? 30-6	
146	1 Rouse (alley)	✓				✓	OK	L							✓+	YR ? 30-6	
160	505 Veilleux.	✓				✓	OK.	L							✓+	YR. 1962 35-5	See. only.
92	502 Veilleux.	✓				✓	OK	L							✓+		See. only.
93	506 Veilleux.	✓				✓	OK	L							✓+	YR. 85 35-4	See. only.
159	507 Veilleux.	✓	✓	✓		✓	OK.	L							✓+	YR. 1962 35-5	
158	513 Veilleux.	✓	✓			✓	OK.	L							✓+	HEPC 63	

Hearst Power Distribution Company Limited
System Assessment Survey

Date: Apr. 20, 2010 Performed by: Mauc

Page No.: 25

26

Abbreviations: VH Very High H High MH Medium-High M Medium ML Medium-Low L Low
P Pole PL Primary Lines TX Transformers I Insulators SS Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed					Comments	
		P	PL	TX	I	SS			2010	2011	2012	2013	2014		2015
94	514 Veilleux	✓				✓	OK	L						✓+	See. only.
157	521 Veilleux.	✓	✓			✓	OK.	L						✓+	YR. 1962 35-5
95	522 Veilleux.	✓				✓	OK.	L						✓+	See. only.
96	524 Veilleux.	✓				✓	OK	L						✓+	See. only.
156	527 Veilleux.	✓	✓	✓		✓	OK	L						✓+	HEPC 59
97	530 Veilleux.	✓				✓	OK.	L						✓+	See. + guy pole.
155	Veilleux + Mailloux(SS)	✓	✓			✓	OK.	L						✓+	HEPC 68
	Veilleux + Mailloux(SS)	✓	✓			✓	OK	L						✓+	YR 2005 40-4
162	7 Mailloux.	✓	✓	✓		✓	OK.	L						✓+	YR 1968 40-4
161	Mailloux.	✓	✓			✓	Cracks in pole.	L						✓+	YR. 1957 35-7 Monitor
46	Hwy 11E + Mailloux.	✓	✓			✓	OK.	L						✓+	YR 1974 45-3
47	Mailloux (M. welding)	✓				✓	OK.	L						✓+	HEPC 71 600V sec.
45	Mailloux (M. welding)	✓	✓	✓	✓	✓	Wood pin X-arm.	L						✓+	YR. 1959 40-5 Pole OK.
	Mailloux + Tremblay(SS)	✓				✓	OK.	L						✓+	YR 2004 35-4
	Mailloux + Tremblay (NW)	✓	✓			✓	Untreated pole.	L						✓+	Monitor condition
	Mailloux + Tremblay (NE)	✓	✓			✓	Minor damage near bottom	L						✓+	WOOD Pin X-arm Monitor cond. YR 1958 40-5
37	534 Tremblay.	✓	✓	✓		✓	Minor damage near bottom	L						✓+	Monitor cond. HEPC 60
40	533 Tremblay.	✓				✓	OK.	L						✓+	YR? 30-? See. only
	531 Tremblay.	✓				✓	OK.	L						✓+	See. only.
	526 Tremblay.	✓	✓		✓	✓	Pole ok - Brown ins.	L						✓+	HEPC 70
40	Tremblay + Blanchard	✓				✓	OK.	L						✓+	HEPC 60
35	522 Tremblay.	✓	✓	✓	✓	✓	Wood pin X-arm - Pole OK	L						✓+	Brown insulators.
34	516 Tremblay.	✓	✓		✓	✓	Pole OK - wood pin X-arm	L						✓+	HEPC 60 - Straighten pole

Hearst Power Distribution Company Limited
System Assessment Survey

Date: Apr. 20, 2010 Performed by: Mauc

Page No.: 26

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

27

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed					Comments	
		P	PL	TX	I	SS			2010	2011	2012	2013	2014		2015
42	509 Tremblay	✓				✓	OK.	L						✓+	See. only.
33	510 Tremblay	✓	✓	✓		✓	Pole ok - brown ins.	L						✓+	HEPC 70
32	500 Tremblay	✓	✓			✓	OK. LS-M3-B	L						✓+	HEPC 60 REPLACE WITH GANG OPERATED
43	505 Tremblay	✓					Minor dam @ bot.	L						✓+	Monitor cond. - guy pole.
90	508 Hwy 11 E.	✓	✓				Cracks + damage @ top	L						✓	Monitor cond. YR. 52?
89	510 Hwy 11 E.	✓	✓				OK. minor cracks	L						✓+	YR. 1957 35-7
88	518 Hwy 11 E.	✓	✓				OK.	L						✓+	HEPC 59
87	518 Hwy 11 E.	✓	✓				OK.	L						✓+	HEPC 59
86	Tremblay + Blanc Neige	✓	✓	✓			OK.	L						✓+	YR. 1958 40-5
85	526 Hwy 11 E.	✓	✓				OK.	L						✓+	HEPC 59
84	531 Hwy 11 E.	✓	✓				OK.	L						✓+	YR? 35-7
83	538 Hwy 11 E.	✓	✓				Cracks in pole.	L						✓+	PROTECTED by pole cub
82	538 Hwy 11 E.	✓	✓			✓	Pole ok - Brown bells	L						✓+	YR. 1972 40-4 - broken guy
1360	422 Brisson	✓	✓			✓	Pole ok. - Single lip ins.	L						✓+	
1359	418 Brisson	✓	✓	✓			Pole OK.	L						✓+	
1340	324 Tremblay														
1340	324 Tremblay	✓	✓				OK.	L						✓+	
1341	323 Tremblay	✓					OK - minor cracks	L						✓+	See. only
1342	323 Tremblay	✓					OK.	L						✓+	
1339	328 Tremblay	✓	✓				OK.	L						✓+	
1338	331 Tremblay	✓					OK - minor cracks	L						✓+	See. only
1335	331 Tremblay	✓					OK.	L						✓+	See. only
1337	332 Tremblay	✓	✓	✓			OK.	L						✓+	

Hearst Power Distribution Company Limited
System Assessment Survey

Date: Apr. 20, 2010 Performed by: Mance

Page No.: 21

28

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed					Comments	
		P	PL	TX	I	SS			2010	2011	2012	2013	2014		2015
1332	334 Tremblay.	✓	✓			✓	OK.	✓						✓+	/
1334	333 Tremblay	✓				✓	OK.	✓						✓+	To straighten - See only.
1333	333 Tremblay.	✓				✓	OK. Cedar pole.	✓						✓+	Monitor cond. - See only.
1331	338 Tremblay.	✓	✓			✓	OK.	✓						✓+	
1330	337 Tremblay.	✓				✓	OK.	✓						✓+	YR.? 35-? See only.
1329	343 Tremblay.	✓				✓	OK.	✓						✓+	YR 1987 See only.
1336	342 Tremblay.	✓	✓	✓		✓	OK.	✓						✓+	YR. 1988 40-4
1327	Chalykoff + Tremblay	✓	✓			✓	OK.	✓						✓+	
1328	347 Tremblay.	✓				✓	OK.	✓						✓+	See only.
1325	353 Tremblay.	✓				✓	OK.	✓						✓+	See only.
1326	354 Tremblay.	✓	✓			✓	OK.	✓						✓+	
1324	Quirion + Tremblay (NE)	✓	✓		✓	✓	OK - Brown bell	✓						✓+	
1323	Quirion + Tremblay (SE)	✓				✓	OK.	✓						✓+	Guy + see pole.
	3 Quirion.	✓				✓	OK.	✓						✓+	See only.
	4 Quirion.	✓				✓	OK.	✓						✓+	YR. 2008 35-4
	402 Hwy 11 E.	✓				✓	OK.	✓						✓+	See only.
1320	400 Tremblay.	✓	✓			✓	Cracks in pole	✓						✓+	Monitor cond. - straighten
1322	403 Tremblay.	✓				✓	OK.	✓						✓+	See only. HEPC 60
1321	405 Tremblay.	✓				✓	OK.	✓						✓+	See only - install guy.
	407 Tremblay.	✓				✓	OK.	✓						✓+	See only (in yard) YR 1970 30.
1319	407 Tremblay.	✓				✓	OK.	✓						✓+	See only HEPC 60
1318	404 Tremblay.	✓	✓	✓		✓	OK.	✓						✓+	HEPC 60
1316	412 Tremblay.	✓	✓			✓	OK.	✓						✓+	HEPC 60

Hearst Power Distribution Company Limited

System Assessment Survey

Date: Apr. 21, 2010 Performed by: Marc

Page No.: 38

29

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed					Comments	
		P	PL	TX	I	SS			2010	2011	2012	2013	2014		2015
1317	415 Tremblay	✓				✓	Minor dam. near bot.	L						✓+	HEPC 67 - Monitor cond.
1315	417 Tremblay	✓				✓	OK.	L						✓+	HEPC 53 See-only.
1314	420 Tremblay	✓	✓	✓		✓	minor cracks in pole.	L						✓+	Monitor condition
1313	421 Tremblay	✓				✓	OK.	L						✓+	
1312	Picard + Tremblay	✓	✓		✓	✓	Pole OK. - Brown ins.	L						✓+	
1310	424 Tremblay	✓	✓			✓	Pole OK. - Brown bells	L						✓+	HEPC 60 - old brown switch
	423 Tremblay	✓				✓	Group in bottom of pole	L						✓+	Monitor cond. - See-only.
1343	7 Picard	✓	✓			✓	OK.	L						✓+	HEPC 56 - tighten guy.
1345	7 Picard	✓	✓			✓	OK.	L						✓+	HEPC 58
1347	9 Picard	✓	✓	✓		✓	Cracks in pole.	L						✓+	HEPC 58 - Monitor cond.
1348	11 Picard	✓	✓			✓	Cracks in pole.	L						✓+	Monitor cond.
	11 Picard (backyard)	✓				✓	OK.	L						✓+	HEPC 72
1350	13 Picard	✓	✓			✓	OK.	L						✓+	
1352	15 Picard	✓	✓			✓	Surface spm dam.	L						✓+	Monitor cond.
1354	17 Picard	✓	✓			✓	OK.	L						✓+	HEPC 61
1356	19 Picard	✓	✓	✓		✓	OK.	L						✓+	HEPC 54
1358	21 Picard	✓	✓			✓	Minor moss on pole	L						✓+	Monitor cond.
1357	22 Picard	✓				✓	OK.	L						✓+	See-only.
1355	20 Picard	✓				✓	OK.	L						✓+	See-only.
1353	18 Picard	✓				✓	OK.	L						✓+	See-only.
1351	16 Picard	✓				✓	OK.	L						✓+	Grey pole.
1349	14 Picard	✓				✓	OK.	L						✓+	See-pole.
1346	10 Picard	✓				✓	Stamp at 6'	ML						✓	Monitor depth + straighten.

Hearst Power Distribution Company Limited
System Assessment Survey

Date: Apr. 21, 2010 Performed by: Marc

Page No.: 28
30

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed					Comments		
		P	PL	TX	I	SS			2010	2011	2012	2013	2014		2015	
1344	8 Picard	✓				✓	OK-	L							✓+	See - only
1	583 N	✓	✓		✓	✓	Pole OK - Brown bellis	L							✓+	YR. 1967 40-4
2	583 N	✓	✓		✓		Pole OK - Brown ins.	L							✓+	YR 19?? 40-4
3	583 N	✓	✓		✓		Spun damage @ bottom	L							✓+	HEPC 74 - Single lip ins.
4	583 N	✓	✓				OK.	L							✓+	YR? 40-4
5	583 N	✓	✓				Cracks in pole.	L							✓+	Monitor cond - joint use w/ H1
6	583 N	✓	✓			✓	Crack @ bottom.	L							✓+	Monitor cond - joint use w/ H1
	Substation	✓	✓	✓		✓	OK. - metering unit	L							✓+	YR. 2005 45-3
7	Substation M3 LBS	✓	✓				OK - LS-M3-M	L							✓+	YR 1973 40-4
	Substation (corner)	✓	✓				OK.	L							✓+	YR 2000 45-4
	Substation (inside fence)	✓	✓				OK.	L							✓+	YR 1974 40-4
9	583 N.	✓	✓				OK.	L							✓+	HEPC 76 - joint use w/ H1
10	583 N	✓	✓	✓		✓	Cracks in pole.	L							✓+	monitor condition.
11	172 583 N	✓	✓	✓		✓	OK.	L							✓+	YR 1964 40-5
12	583 N	✓	✓				Cracks in pole	L							✓+	Monitor condition
13	583 N	✓	✓				OK.	L							✓+	YR? 40-5
14	583 N	✓	✓				OK.	L							✓+	YR? 40-5
15	583 N	✓	✓				Minor cracks	L							✓+	Monitor cond. 40-5
16	583 N	✓	✓				Minor dam. near bot.	L							✓+	Monitor cond.
17	583 N	✓	✓				Minor cracks @ bottom	L							✓+	Monitor cond.
18	583 N	✓	✓	✓			OK.	L							✓+	
19	150 583 N	✓	✓			✓	OK.	L							✓+	
20	583 N	✓	✓				OK.	L							✓+	YR. 1964 - 40-5

Hearst Power Distribution Company Limited

System Assessment Survey

Date: Apr. 21, 2010 Performed by: Mare

Page No.: 30
31

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed					Comments		
		P	PL	TX	I	SS			2010	2011	2012	2013	2014		2015	
21	583N 583N	✓	✓				OK.	L							✓+	
	Brisson + 583N	✓					OK.	L							✓+	YR. 1996 35-4 - guy pole.
22	583 N.	✓	✓				OK.	L							✓+	YR 1964 40-5
23	583 N	✓	✓			✓	OK.	L							✓+	YR 1964 40-5
24	Veilleux + 583N	✓	✓			✓	OK.	L							✓+	YR 1976 40-4
25	8 583 N.	✓	✓			✓	Pole OK - moss on X-arm	L							✓+	
26	Tremblay + 583 N.	✓	✓			✓	Exterior of pole rough	L							✓	YR. 1964 45-4
27	(Exempt) 583N	✓	✓				OK.	L							✓+	YR. 1996 45-4
28	Hwy 11E + 583N	✓	✓				OK.	L							✓+	YR. 1996 45-2
29	Hwy 11E (Exempt 3rd bank)	✓	✓			✓	OK.	L							✓+	YR 1988 ?-4
30	Hwy 11E (OCWA boosted)	✓	✓	✓	✓	✓	Exterior rough.	L							✓	Monitor cond. - Brown. Ins.
	Hwy. 11E + 583N (Subk)	✓					OK.	L							✓+	guy pole.
256	Kabelle + Hwy 11W.	✓	✓			✓	OK.	L							✓+	YR. 1972 50-4
257	1697 Hwy 11W	✓	✓			✓	OK.	L							✓+	YR. 1996 45-3
258	1691 Hwy 11W.	✓	✓	✓		✓	OK.	L							✓+	YR 1996 45-3
259	1687 Hwy 11W (scale)	✓	✓	✓	✓	✓	Moss on X-arm - single dip ins.	L							✓+	Monitor cond. YR 1972 40-5
260	1687 Hwy 11W (scale)	✓	✓				Moss on X-arm - single dip ins.	L							✓+	YR. 1972 40-5
261	1671 Hwy 11W (MTO)	✓	✓		✓	✓	Moss on X-arm - Single dip ins.	L							✓+	YR ? 45-5
	MTO YARD	✓	✓	✓	✓	✓	Pole OK. - Brown bells	L							✓+	TX Rusty
262	Hwy 11W.	✓	✓		✓		Pole OK. - Single dip ins.	L							✓+	YR. 1972 40-4
263	Hwy. 11W.	✓	✓				OK.	L							✓+	YR 1996 45-3
264	1605 Hwy 11W.	✓	✓	✓		✓	OK.	L							✓+	YR. 1996 45-3
265	1605 Hwy. 11W.	✓	✓			✓	OK.	L							✓+	YR. 1996 45-3

Hearst Power Distribution Company Limited
System Assessment Survey

Date: Apr. 21, 2010 Performed by: Mave

Page No.: 31
32

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed						Comments
		P	PL	TX	I	SS			2010	2011	2012	2013	2014	2015	
266	Hwy. 11W (MAKI)	✓	✓		✓	✓	Spur damage on pole.	L						✓+	Single lip insulators.
267	Husky (behind fuel tanks)	✓				✓	OK.	L						✓+	Remove pole? Not in use.
268	Maki's yard.	✓	✓	✓		✓	OK.	L						✓+	OLD TX - 915TP
269	Maki 3rd bank.	✓	✓	✓		✓	OK.	L						✓+	
270	Husky. west entrance	✓	✓		✓	✓	Pole OK - Single lip ins.	L						✓+	
271	Husky. 3rd bank	✓	✓	✓	✓	✓	Pole OK - Single lip ins.	L						✓+	YR? 45-? minor rust on TX's
386	1554 Hwy 11W.	✓				✓	Pole OK.	L						✓+	Claude Villeneuve Plug ins.
	1554 Hwy 11W.	✓	✓				OK.	L						✓+	YR 2000 40-4 Villeneuve const dip ps
273	Villeneuve office.	✓	✓			✓	OK.	L						✓+	YR 1996 45-3
	Villeneuve yard.	✓				✓	OK.	L						✓+	YR 2000 35-4 - Lecons lumber plug
	Lecons lumber office	✓	✓	✓		✓	OK - minor rust on TX.	L						✓+	Villeneuve yard.
	old Villeneuve const (back)	✓	✓	✓			Tighten guy wires	L						✓+	
276	old Villeneuve const. 3rd	✓	✓	✓	✓	✓	Pole OK - Single lip ins.	L						✓+	
277	Villeneuve office.	✓	✓	✓	✓	✓	Pole OK - Single lip ins.	L						✓+	
384	1554 Hwy 11W (entrance)	✓					OK.	L						✓+	Guy pole.
278	Independant LBS	✓	✓			✓	OK.	L						✓+	YR. 1992 - 45-4
	Independant dip pole	✓	✓				OK.	L						✓+	YR 2002 - 45-4
	Independant. 2nd pole	✓	✓				OK.	L						✓+	YR 2006 40-4
279	McDonald's dip pole	✓	✓		✓	✓	Pole OK - Single lip ins.	L						✓+	
280	McDonald's Hwy 11W	✓	✓			✓	Pole OK - Single lip ins.	L						✓+	
	Hwy 11W M2 LBS	✓	✓			✓	OK. LS-M2-3B	L						✓+	YR. 2004 45-3
1415	Fontaine DR. (west)	✓	✓	✓		✓	OK.	L						✓+	
1414	Fontaine DR.	✓	✓	✓		✓	OK.	L						✓+	

Hearst Power Distribution Company Limited

System Assessment Survey

Date: Apr. 21, 2010 Performed by: Mare

Page No.: 32
33

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed						Comments
		P	PL	TX	I	SS			2010	2011	2012	2013	2014	2015	
1413	Fontaine DR. (west)	✓	✓			✓	minor damage near bot.	L						✓+	Monitor condition
	200 Fontaine DR.	✓				✓	OK.	L						✓+	Tembec Plug ins.
1412	Fontaine DR (west)	✓	✓				OK.	L						✓+	
1411	Fontaine DR (west)	✓	✓			✓	Pole ok - Brown bells	L						✓+	
1410	Fontaine DR (Tracks)	✓	✓			✓	OK.	L						✓+	✓R 1996 - 35-4 see. only
1409	Fontaine DR (tracks)	✓				✓	OK.	L						✓+	✓R 1996 35-4 see. only.
1408	Fontaine DR (tracks)	✓				✓	OK.	L						✓+	Install guy wire?
	Fontaine DR. (tembec scale)	✓				✓	OK.	L						✓+	✓R 2000 35-4
AK2V8P	Fontaine DR.	✓	✓	✓		✓	OK.	L						✓+	tighten guy wires.
AK2V9U	Fontaine DR.	✓	✓				OK	L						✓+	
AK2V12	Fontaine DR.	✓	✓				OK.	L						✓+	✓R. 2000 40-4
next to ↑	Fontaine DR.	✓					Monitor gauge near bot.	L						✓+	Monitor cond. - guy pole
870-85	Fontaine DR.	✓	✓			✓	Pole ok - wood pin X-arm	L						✓+	
	148 Fontaine DR	✓	✓	✓		✓	OK.	L						✓+	✓R 1991 40-4 - Straighten pole
	144 Fontaine DR	✓	✓	✓		✓	OK.	L						✓+	✓R 1991 40-4
-38-	Fontaine DR.	✓	✓			✓	Pole ok - Wood pin X-arm	L						✓+	
	Fontaine DR.	✓	✓			✓	Pole ok - Wood pin X-arm	L						✓+	
-90-	Fontaine DR.	✓	✓			✓	Pole ok. - Wood pin X-arm	L						✓+	Straighten pole - severe lean.
-91-	100 Fontaine DR.	✓	✓			✓	Pole ok. - wood pin X-arm	L						✓+	HEPC 58
-92-	100 Fontaine DR.	✓	✓			✓	Pole ok - Wood pin X-arm	L						✓+	HEPC 59
-93-	Fontaine DR.	✓	✓	✓		✓	Pole ok. - Wood pin X-arm	L						✓+	HEPC 59
-867-	94 Fontaine DR	✓	✓			✓	Large gauge near bottom	M							
-95-	Fontaine DR.	✓	✓			✓	Cracks in pole - wood pin X-arm	L						✓+	Monitor condition HEPC 59

(✓) est.

X-arm

Hearst Power Distribution Company Limited

System Assessment Survey

Date: Apr. 22, 2010

Performed by: Mauc.

Page No.: 33

34

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed					Comments	
		P	PL	TX	I	SS			2010	2011	2012	2013	2014		2015
-96	86 Fontaine DR.	✓	✓	✓	✓	✓	Pole OK - wood pin X-arm L							✓+	HEPC 37
	84 Fontaine DR.	✓	✓		✓	✓	Spun damage - wood pin X-arm L							✓+	Monitor condition.
	Fontaine DR (Tembec ^{west} ant.)	✓	✓		✓	✓	Pole OK - Brown bells L							✓+	YR 1979 35-6
	Fontaine DR (Tembec park)	✓	✓	✓		✓	OK.							✓+	YR 2003 40-4
	Fontaine PR (Tembec park)	✓				✓	OK.							✓+	YR 2003 35-4
84	Fontaine DR.	✓					OK.							✓+	guy pole (J.G. Caron).
	J.G. Caron. line	✓	✓				OK.							✓+	1st pole from south.
	J.G. Caron. line	✓	✓				OK.							✓+	2nd pole from south.
	J.G. Caron line	✓	✓			✓	OK.							✓+	YR 2002 45-4 south of Marchildon
	J.G. Caron line.	✓	✓	✓		✓	OK.							✓+	YR 2002 45-4 north of Marchildon
	J.G. Caron line.	✓	✓				OK.							✓+	2nd pole from house.
	J.G. Caron line.	✓	✓	✓			OK.							✓+	YR 1995 40-4 - Pole near house.
	CAN TIRE line (1st fr HI)	✓	✓				OK.							✓+	YR 2007 45-4
	CAN TIRE line (2nd fr HI)	✓	✓				OK.							✓+	YR 2007 45-5
	CAN TIRE line (3rd fr HI)	✓	✓				OK.							✓+	YR 2007 45-4
	CAN TIRE LBS (4th fr HI)	✓	✓				OK.							✓+	YR 2007 45-3
	CAN TIRE dead-end (5th fr HI)	✓	✓				OK.							✓+	YR 2007 45-4

Hearst Power Distribution Company Limited

System Assessment Survey

 Date: Apr. 22, 2010

 Performed by: Mare

 Page No.: 34

35

Abbreviations: VH Very High H High MH Medium-High M Medium ML Medium-Low L Low
 P Pole PL Primary Lines TX Transformers I Insulators SS Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed					Comments	
		P	PL	TX	I	SS			2010	2011	2012	2013	2014		2015
1372	200 583N	✓				✓	OK	L						✓+	HEPC 54 see only
200	200 583N	✓				✓	OK.	L						✓+	YR 2004 35-4 see only
1362	Algonquin/Shelak subs	✓				✓	OK minor damage at bottom	L						✓+	Monitor condition see only
1371	Dump.	✓	✓				Small gouge at bottom.	L						✓+	Monitor condition
1370	Dump.	✓	✓				OK	L						✓+	YR? 35-7
1369	Dump	✓	✓				OK.	L						✓+	YR 2006 40-4
1368	Dump.	✓	✓			✓	OK	L						✓+	YR 2006 45-4
1367	Dump.	✓	✓			✓	Large gouge @ bottom	L						✓	Monitor condition.
1366	Dump	✓	✓	✓		✓	Minor damage to pole	L						✓	Monitor condition
1365	Dump.	✓	✓				Pole ok - Broken tie.	L						✓+	HEPC 51
1364	Dump.	✓	✓				OK.	L						✓+	
1363	Dump (dead-end)	✓	✓				Cracks in pole	L						✓+	Monitor condition
1215	Bergeron + Barrette	✓	✓			✓	OK.	L						✓+	YR 1996 40-4
1214	2 Barrette	✓	✓	✓	✓	✓	Pole ok. - Brown beels	L						✓+	HEPC 68
	314 Bergeron (back alley)	✓				✓	OK.	L						✓+	See only.
	310 Bergeron. (back alley)	✓				✓	OK.	L						✓+	See only.
	306 Bergeron (back alley)	✓				✓	OK.	L						✓+	See only.
1282	326 Bergeron.	✓				✓	OK.	L						✓+	See only.
1281	320 Bergeron.	✓				✓	OK.	L						✓+	See only.
1280	318 Bergeron.	✓				✓	OK.	L						✓+	HEPC 62
	404 Hwy 11 E.	✓	✓	✓		✓	OK.	L						✓+	YR 1968 40-4
	410 Hwy 11 E.	✓				✓	OK.	L						✓+	See only.

Hearst Power Distribution Company Limited

System Assessment Survey

Date: Apr 30 / 10

Performed by: Marc

Page No.: 36

37

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed						Comments	
		P	PL	TX	I	SS			2010	2011	2012	2013	2014	2015		
411	1131 George-	✓	✓			✓	OK.	L							✓+	YR. 1987. 40-3
412	1121 George.	✓	✓	✓		✓	OK.	L							✓+	YR. 1987 40-3
413	1115 George.	✓	✓			✓	OK.	L							✓+	YR 1966 35-?
424	1116 George.	✓				✓	OK.	L							✓+	See. only
414	1105 George	✓	✓	✓		✓	OK.	L							✓+	
	11th + George.	✓	✓			✓	OK.	L							✓+	YR. 1990 40-4 → Straighten
H17	Hearst Supermarket parking	✓	✓			✓	Minor damage to bot.	L							✓+	Monitor condition - YR 1966 35-
418	1021 George.	✓	✓	✓		✓	Pole OK - tx minor leak.	L							✓+	YR. 1987 40-3
419	1013 George.	✓					OK.	L							✓+	guy pole.
420	1013 George.	✓	✓			✓	Minor gouge near bot.	L							✓+	Monitor cond.
421	1007 George.	✓	✓	✓		✓	Minor scrape at bottom	L							✓+	Monitor cond. - YR. 1969 40-6
422	10th. + George.	✓	✓			✓	OK. - tighten guy.	L							✓+	YR. 1972 40-5
581	8th + George. (sw)	✓	✓			✓	OK.	L							✓+	Repair ground. moulding.
	Hearst lumber yard.	✓				✓	OK.	L							✓+	YR 2007 35-4
580	727 George.	✓	✓			✓	OK. - Straighten.	L							✓+	
	727 George.	✓				✓	OK.	L							✓+	See. only.
	727 George.	✓				✓	OK - tighten guy.	L							✓+	HEPC 65
579	717 George.	✓	✓			✓	OK.	L							✓+	YR. 1990 40-4
	717 George (yard)	✓				✓	Notches cut in pole	L							✓+	Monitor condition.
577	715 George.	✓	✓			✓	OK.	L							✓+	YR. 1990 40-4.
578	Hearst lumber yard	✓					OK.	L							✓+	guy pole.
576	711 George.	✓	✓	✓		✓	OK.	L							✓+	YR. 2000 40-4.
575	7th + George.	✓	✓			✓	Cracks in pole.	L							✓+	Monitor cond. - YR. 1963 40-5

Hearst Power Distribution Company Limited

System Assessment Survey

Date: Apr 30, 2010 Performed by: Marc

Page No.: 37

39

Abbreviations: **VH** Very High **H** High **MH** Medium-High **M** Medium **ML** Medium-Low **L** Low
P Pole **PL** Primary Lines **TX** Transformers **I** Insulators **SS** Secondary Services

Pole #	Location	Equipment Type					Current Assessment	Priority	Year to be Changed						Comments	
		P	PL	TX	I	SS			2010	2011	2012	2013	2014	2015		
572	7th + George.	✓	✓		✓	✓	Cracks in pole:	L							✓+	Single leg insulator.
573	Andre's Comm.	✓	✓	✓		✓	OK.	L							✓+	YR. 1972 40-4
571	625 George.	✓	✓	✓		✓	OK.	L							✓+	YR. 1991 40-4
568	615 George.	✓	✓			✓	OK.	L							✓+	YR. 1991 40-4
569	618 George.	✓				✓	OK.	L							✓+	See. only.
570	622 George	✓				✓	Notches cut in pole.	L							✓+	Monitor cond. YR. 1958 30-5
567	609 George.	✓	✓			✓	OK.	L							✓+	YR. 1991 40-4.
547	6th + George. (SE)	✓	✓			✓	Stamp at 5 1/2' - pole OK.	L							✓+	YR 1981 40-5
549	525 George.	✓	✓			✓	Minor damage near bot	L							✓+	Monitor cond.
550	515 George.	✓	✓			✓	Cracks in pole.	L							✓+	Monitor cond. - YR. 1969 40-5
551	507 George.	✓	✓			✓	OK.	L							✓+	YR 1952 40-5
552	5th + George (SW)	✓	✓	✓		✓	OK.	L							✓+	YR 1929 40-5
553	5th + George. (SE)	✓	✓			✓	OK.	L							✓+	
560	421 George.	✓	✓		✓	✓	Pole ok. Brown bell	L							✓+	
561	415 George.	✓	✓	✓		✓	OK.	L							✓+	YR. 1975 35-5
562	411 George.	✓	✓	✓		✓	OK.	L							✓+	YR. 2000 40-4
563	401 George.	✓	✓			✓	OK.	L							✓+	
563-1	P. Paulin yard.	✓	✓			✓	OK.	L							✓+	
564	P. Paulin yard.	✓	✓			✓	OK.	L							✓+	YR. 1998 40-4
565	CFP Parking (George)	✓				✓	OK.	L							✓+	600V see.
566	CFP Parking (George)	✓				✓	OK.	L							✓+	600V see.
	425 FRONT.	✓				✓	OK.	L							✓+	YR. 1970 35-4 See. only
556	5th + FRONT.	✓				✓	OK.	L							✓+	See. only.

