

TILTRAN SERVICES INC.

Electrical Power System Specialists

July 5, 2010

Erie Thames Power
280 Elm Street
Aylmer, ON
N5C 3G3

Attention: *Mr. Chris White, Chief Operating Officer*

Re: Maintenance Inspection Report -- Our Ref. No. 23403LSP
Clinton Power – 2 Sites – semi-annual inspections

Dear Chris,

Please find attached the report for the semi-annual inspections completed May 20, 2010 at two locations.

Tiltran Services cleaned, serviced and tested as required the main power system. All testing results were satisfactory with no faults found. A summary of the site findings is listed below for your review.


MSI

Findings/ Repairs:

- Some barbed wire is rusty but still strong
- Various sections of the fence are unbonded




- Nameplate found faded



- Fans installed but not connected

Recommendations:

- Replace ceramic lightning arrestors on pole switch to polymer



MS2

Findings/ Repairs:

- Only one bond found on each transformer
- Oil found seeping from level gauges. Gauges are hard to read due to oil stains



- Photo cell on lights tested satisfactory – instant on and off
- Liquid tight on right east light – pulled out, trimmed and reset



All other equipment that we tested appears in satisfactory condition, suitable for continued service.

Please give us a call should you wish us to provide you pricing and services for any or all of the recommended repairs listed in this report.

If you have any questions/concerns please do not hesitate to contact me. We look forward to being of continued service to Clinton Power.

Sincerely,
TILTRAN SERVICES INC.



Doug Charron
Master Electrician, Technician
Maintenance and Technical Services
Phone: (519) 842-6458 Ext 227
Fax: (519) 842-2496
Cell: (519) 521-2600