

Enbridge Gas Distribution Inc.
PO Box 650
Scarborough, ON, M1K 5E3
Canada
www.enbridge.com/gas

Ritch Murray, MBA, PEng
Project Manager
Engineering Special Projects
Tel 416 495 6502
Fax 416 495 6530
ritchie.murray@enbridge.com



05-May-2011

File Number: 30.5859503.09

Ms. Kirsten Walli
Board Secretary
Ontario Energy Board
PO Box 2319
2300 Yonge St, Suite 2700
Toronto, ON, M4P 1E4

Dear Ms. Walli:

Re: Natural gas pipeline serving York Energy Centre("YEC"), EB-2009-0187

This letter is in response to enquiries about pipeline construction, and in particular the use of horizontal directional drilling ("HDD") and drilling fluid ("bentonite"), along Lloydtown-Aurora Road in Pottageville, Ontario. There have been two cases where inadvertent returns of drilling fluid ("spill" or "frac-out") have impacted private property such that reinstatement will be required. To protect the individuals involved, it is requested that personal information contained in this letter be redacted in the event it is to be made publically available.

The first case involves a residence located at [REDACTED] Drilling fluid inadvertently returned in the backyard of this property. The backyard will require reinstatement, which Enbridge will undertake. In addition, as the property owner has expressed concerns about the quality of his well water, Enbridge has, without prejudice, provided an alternative source of potable water and is reimbursing the property owner for the cost of bottled drinking water. Enbridge has engaged Stantec Consulting to assess the water supply for any impact from the drilling fluids and to recommend remedial measures if necessary.

The second case involves the [REDACTED] refueling station and convenience store located at [REDACTED] Drilling fluid inadvertently returned in the refueling area / parking lot of this property. Enbridge engaged TankTek Environmental Services Ltd. to test the below ground storage tanks and pump supply lines. The report from TankTek on the tanks and lines concluded that the underground storage tank systems at the site passed inspection and are tight, with the result that the inadvertent return did not impact upon the integrity of the tanks. Enbridge has shared the test results with the owner. Golder & Associates have been asked to

2011-05-05

Page 2

advise what steps, if any, should be taken. Enbridge will work with the property owner with respect to this issue.

In both cases, the inadvertent returns were reported as required to the Spills Action Centre, York Region, and Lake Simcoe Regional Conservation Authority. The Ministry of the Environment is aware of both cases and has been on-site to investigate.

Regards.

A handwritten signature in blue ink, appearing to read 'R. Murray', with a stylized flourish at the end.

R. Murray, PEng
Project Manager, YEC Pipeline Project

cc: Zora Crnojacki, Project Advisor, Applications and Regulatory Audit, Ontario Energy Board.
Neil McKay, Manager, Natural Gas Applications, Ontario Energy Board.
Edith Chin, Manager Upstream Regulatory Strategy and Major Projects, Enbridge.