

**Amanda Klein**

Director, Regulatory Affairs  
Toronto Hydro-Electric System Limited  
14 Carlton Street  
Toronto, Ontario M5B 1K5

Telephone: 416.542.2729  
Facsimile: 416.542.3013  
[regulatoryaffairs@torontohydro.com](mailto:regulatoryaffairs@torontohydro.com)  
[www.torontohydro.com](http://www.torontohydro.com)



December 6, 2012

*via RESS e-filing – signed original to follow by courier*

Ms. Kirsten Walli  
Board Secretary  
Ontario Energy Board  
PO Box 2319  
2300 Yonge Street, 27<sup>th</sup> floor  
Toronto, ON M4P 1E4

Dear Ms. Walli:

**Re: Toronto Hydro-Electric System Limited (“THESL”)  
OEB File No. EB-2012-0064 (the “Application”)  
Corrections to Evidence and Technical Conference Undertaking Response**

---

THESL writes in respect of the above-noted matter.

Please find enclosed a correction to THESL's pre-filed evidence in respect of Tab 4, Schedule B7. Due to a technical error, a page was inadvertently left blank in the Polymer SMD-20 Switches business case. The complete page is enclosed.

Also attached is a corrected active Excel appendix to Technical Conference Undertaking JT1.15. The previously filed appendix incorrectly provided Windsor TS data in place of Terauley TS data. Changes to the appendix are highlighted in red.

Please do not hesitate to contact me if you have any questions.

Yours truly,

*[original signed by]*

**Amanda Klein**

Director, Regulatory Affairs  
Toronto Hydro-Electric System Limited  
[regulatoryaffairs@torontohydro.com](mailto:regulatoryaffairs@torontohydro.com)

:AK/RB

cc: Fred Cass of Aird & Berlis LLP, Counsel for THESL, by electronic mail only  
Intervenors of Record for EB-2012-0064 by electronic mail only

## ICM Project | Polymer SMD-20 Switches Segment

### 1 Appendix 3 – Letter from HD Supply – Utilities, November 2011



Box 399, 188 Purdy Road  
Colborne, ON K0K 1S0  
P: 905-355-2474  
F: 905-355-3054

ISO 9001:2000



005841

November 28, 2011

Dear Valued Customer:

Our records indicate that you have purchased from HD Supply, SMD-20 fuses with polymer insulators, manufactured by S&C. According to the attached letter we recently received from S&C, there is a possibility that the insulator may break when a lineman opens the fuse using a Loadbuster Tool.

We therefore recommend that you carefully review the attached letter describing the events that may lead to a broken insulator while opening the fuse. Please inform your operating personnel of such risks, and identify any fuses in use and contact us at 1-800-263-7738, so that we can develop a remediation plan for you.

We apologize for any inconvenience and look forward to working with you and S&C to remedy this situation as quickly and safely as possible.

Yours truly,

A handwritten signature in black ink, appearing to read 'Gary Walker'.

Gary Walker  
VP Canada  
HD Supply Utilities