

79 Wellington St. W., 30th Floor Box 270, TD South Tower Toronto, Ontario M5K 1N2 Canada P. 416.865.0040 | F. 416.865.7380 www.torys.com

April 3, 2014

RESS & COURIER

Ontario Energy Board P.O. Box 2319 27th Floor 2300 Yonge Street Toronto, Ontario M4P 1E4

Attention: Ms. K. Walli, Board Secretary

Dear Ms. Walli:

Re: EB-2014-0139 – Jericho Wind, Inc. ("Jericho") Section 41(9) Application (the "Application") – Administrative Correction to the Application

We are legal counsel to Jericho in the above noted proceeding, and are writing to correct an administrative error in the Application.

By way of background, in the Application, Jericho requests that the Board determine the location of Jericho's distribution facilities within certain Lambton County road allowances, all in accordance with Exhibit B, Tab 6, Schedule 1 of the Application. For ease of reference, Jericho also included with the Application a map (located at Exhibit B, Tab 2, Schedule 1, Appendix A) that gives a high level overview of where in the County's road allowances that Jericho's distribution facilities will be located (the "Original Overview Map"). In issuing the Notice of Application and Written Hearing (the "Notice"), the Board included a copy of the Original Overview Map and required it to be served on the relevant parties.

In preparing to serve the Notice, Jericho identified certain administrative errors in the Original Overview Map. In particular, certain stretches of Lambton County road allowances were misclassified as not containing Jericho's distribution facilities when in fact they will contain those facilities. Jericho has corrected these errors in an updated version of the overview map, which is attached hereto at Appendix "A" (the "Corrected Overview Map").

With this letter, Jericho would like to request that the Application be amended such that the Original Overview Map be replaced with the Corrected Overview Map in Exhibit B, Tab 2, Schedule 1, Appendix A of the Application. In addition, Jericho requests confirmation that a copy of the Corrected Overview Map should be served with the Notice (rather than a copy of the Original Overview Map).

Finally, Jericho notes that the only errors were in the Original Overview Map; there are no errors in the more detailed engineering diagrams that are included in the Appendices to Exhibit B, Tab 6, Schedule 1 of the Application. Therefore, the administrative errors described above do

not affect Jericho's request that the location of its distribution facilities be determined in accordance with the proposal set out in Exhibit B, Tab 6, Schedule 1.

Please feel free to contact me with any questions.

Yours truly,

Tyson Dyck

Tel 416.865.8136 Fax 416.865.7380 tdyck@torys.com

cc:

N. Mikhail, OEB Staff

R. Groffman, NextEra Energy
B. Greenhouse, NextEra Energy
A. Pinnock, NextEra, NextEra Energy

APPENDIX "A" - CORRECTED OVERVIEW MAP

