

## **Project Information**

| Project Name: | Substation Condition Assessment |
|---------------|---------------------------------|
| Project #:    | 30934                           |
| Description:  | Amendment Memo                  |
| Document:     | Memo #1                         |

Electrical Engineer of Record: Spark Power High Voltage Services Inc. 1315 North Service Road East Oakville, Ontario L6H 1A7

## **Revision Log**

| Revision | Date       | Prepared by: | Reviewed by: | Approved by: | Description      |
|----------|------------|--------------|--------------|--------------|------------------|
| 01       | 2021-04-30 | RSG          | -            | -            | Issued to Client |
| 02       | 2021-05-06 | НН           | -            | -            | Issued to Client |

Since the completion of Revision 1 of the Substation Condition Assessment in March 2020, Rideau St. Lawrence Distribution has completed minor upgrades and repair work which has had a minor impact in improving the condition of their substations. These upgrades or work has included:

- Identification of spare fuse inventory located at the Prescott, ON office.
- Completed ground connection repairs within substations at Morrisburg MS1, Morrisburg MS2, Iroquois MS, and Prescott MS4
- Provided device nomenclature and
- Repaired the flexible bus leads at Cardinal MS1
- Replaced the ground mat at Prescott MS3

These repairs have resulted in the following changes in total station scores:

| Station      | Original Station<br>Score | New Station<br>Score |
|--------------|---------------------------|----------------------|
| Cardinal MS1 | 2.6                       | 2.9                  |
| Cardinal MS2 | 3.1                       | No change            |
| Iroquois MS  | 3.3                       | No change            |
| Morrisburg   | 3.1                       | 3.2                  |
| MS1          |                           |                      |
| Morrisburg   | 2.7                       | No change            |
| MS2          |                           |                      |
| Prescott MS1 | 3.8                       | No change            |
| Prescott MS2 | 3.3                       | No change            |
| Prescott MS3 | 2.8                       | 3.2                  |
| Prescott MS4 | 3.0                       | No change            |

CONFIDENTIAL



The remaining recommendations for station improvements remain intact and should be pursued in accordance with the table of priorities provided in the Condition Assessment as the repairs noted above have not impacted station priorities.

In discussion with operations personnel, the following options have been outlined at a high level:

- Adding an additional transformer T2 at Morrisburg MS1, with additional feeders out of the substation & a tie system to Bus 1
- Decommissioning of Morrisburg MS2 and relocation of T1 to Prescott MS1.

We believe that these options are prudent and would result in significant improvement to those applicable stations while correcting the immediate priorities of multiple distribution areas, although we acknowledge that further discussion with Rideau St. Lawrence staff is pending and other alternatives may exist.