

Hydro One Networks Inc.

8th Floor, South Tower
483 Bay Street
Toronto, Ontario M5G 2P5
www.HydroOne.com

Tel: (416) 345-5913
Fax: (416) 345-5866
Glen.MacDonald@HydroOne.com

Glen MacDonald

Senior Advisor – Regulatory Research and Administration
Regulatory Affairs



BY COURIER

November 5, 2007

Ms. Kirsten Walli
Secretary
Ontario Energy Board
Suite 2700, 2300 Yonge Street
P.O. Box 2319
Toronto, ON.
M4P 1E4

Dear Ms. Walli:

EB-2007-0050 – Hydro One Networks' Section 92 Bruce - Milton Transmission Reinforcement Application – Transcript Errata for Transcript of the October 15-16 Technical Conference

I am writing to provide transcript errata arising from the October 15-16 Technical Conference. Corrections are detailed in the attached page.

Sincerely,

ORIGINAL SIGNED BY GLEN MACDONALD

Glen MacDonald

Attach.

October 15, 2007

Page #	Line #	Error	Correction
17	9 is soon to be	... is assumed to be
17	17	know that the Bruce Peninsula	notice that there are two major locations
18	5	...will lengthen then the life	...will lengthen the life
19	2	there will they will be	they will be
21	10	Then the resource plot	The resource plot
24	11	...to a reliable set	...to a reasonable set
28	26	5 AC	500 kV AC
33	1	Those are shrink capacitors and possibly SBCs	Those are shunt capacitors and possibly SVCs
34	10	..not just under all those	...not just under outage
39	18	...consists of shrink compensation	...consists of shunt compensation
46	27	higher than the 74	7400 Megawatts
56	15	in terms of low supply,	in terms of load supply,
99	20	The 2009 and 2010 indicator in-service date	The 2009 and 2010 in service facilities will remain into the long term.
166	4	..is four times surge and pins	...is four times surge impedance
166	7	..is four times surge and pins	...is four times surge impedance
182	22	to replace co-	to replace coal
195	18	In summer,	Sometimes,

October 16, 2007

Page #	Line #	Error	Correction
15	21-23	Paragraph is inaccurately situated	Paragraph said and should be shown after line 13 on the same page.