

**Ontario Energy
Board**
P.O. Box 2319
27th. Floor
2300 Yonge Street
Toronto ON M4P 1E4
Telephone: 416- 481-1967
Facsimile: 416- 440-7656
Toll free: 1-888-632-6273

**Commission de l'énergie
de l'Ontario**
C.P. 2319
27e étage
2300, rue Yonge
Toronto ON M4P 1E4
Téléphone: 416- 481-1967
Télécopieur: 416- 440-7656
Numéro sans frais: 1-888-632-6273



BY E-MAIL

December 3, 2014

Attention: Ms. Kirsten Walli, Board Secretary

Dear Ms. Walli:

**Re: East Durham Wind Inc.
Motion to Review and Vary Decision and Order regarding
Location of Distribution Facilities in Public Roadway
Board File Number EB-2014-0337**

In accordance with Procedural Order No. 1 issued on November 21, 2014, please find attached the Board staff interrogatories on the referenced application filed by east Durham Wind Inc.

Original Signed By

Edik Zwarenstein
Project Advisor, Electricity Facilities and Infrastructure

Attachment

cc: All parties

Board Staff Interrogatories
Motion to Review and Vary
the Revised Decision and Order in EB-2013-0233
East Durham Wind Inc. ("East Durham")
EB-2014-0337
December 3, 2014

Reference:

East Durham Wind Inc. request for Motion to Review and Vary
(filed November 3, 2014)

INTERROGATORY Staff-1

Preamble:

There are numerous sections where the cable is placed in horizontally bored channel.

Question/Requests:

- a. What regulations are applicable to ensure safety with respect to possible digging activity such as construction, farming, etc. along the length of the bore-located cable?
- b. What safety markers and other special provisions will be provided by Fairview to identify cable which is located in a horizontally bored channel?

INTERROGATORY Staff-2

Preamble:

Intervenor Parkins has indicated to the Board that their property is affected by this application.

Question/Requests:

- a. Please indicate if any of the proposed route modifications are adjacent to the property owned by the Parkins, and identify which page of the maps is relevant to this modification.
- b. Please describe, if applicable, how in your opinion, the Parkins property might be affected.

- End of document -