Ontario Energy Board Commission de l'énergie

de l'Ontario

P.O. Box 2319 2300 Yonge Street 27th Floor Toronto ON M4P 1E4 C.P. 2319 2300, rue Yonge 27e étage

Telephone: 416-481-1967 Facsimile: 416-440-7656 Toll free: 1-888-632-6273

Toronto ON M4P 1E4 Téléphone: 416-481-1967 Télécopieur: 416-440-7656 Numéro sans frais: 1-888-632-6273



BY Automated E-Mail

September 1, 2016

Jeanne Brown
Pike Lake Golf Centre Limited
Unit P-01
9025 Pike Lake Road R.R. #3
Clifford ON N0G 1M0

Dear Mr. Brown:

Re: Unit Sub-Metering Licence Renewal

Pike Lake Golf Centre Limited - ES-2012-0258

Your Unit Sub-Metering Licence ES-2012-0258 is due to expire on January 29, 2017.

If Pike Lake Golf Centre Limited wishes to continue to participate in the Ontario Electricity market, you are invited to file an application to renew Pike Lake Golf Centre Limited's Unit Sub-Metering Licence. As you are aware, Pike Lake Golf Centre Limited is not permitted to carry out activities described in section 57 of the Ontario Energy Board Act, 1998 (the "Act") without a licence.

The standard time required to issue a licence is 90 days from receipt of a complete application. To assist the Board to renew Pike Lake Golf Centre Limited's licence in a timely manner prior to the expiry date, you are required to submit your application to the Board within 30 days of this e-mail. A licence application form is available on our website at the following address:

http://www.ontarioenergyboard.ca/OEB/Industry/Licences/Apply+for+a+Licence

On receipt of the application, the Board will proceed to review the application for renewal in accordance with Part V of the Act. If we do not receive the application by the required date, the Board will be prepared to remove the name from the licensee records once the current licence is expired.

If you have any questions regarding this process, you may contact George Dimitropoulos, Advisor, at 416 544 5152 or by e-mail at George.Dimitropoulos@ontarioenergyboard.ca.

Yours truly,

Original signed by

John Pickernell Manager, Applications Administration