

VIA Email, RESS and Courier

July 17, 2019

Ms. Kirsten Walli Board Secretary Ontario Energy Board 2300 Yonge Street, Suite 2700 Toronto, Ontario M4P 1E4

Dear Ms. Walli:

Re: Enbridge Gas Inc. (Enbridge Gas)

Ontario Energy Board (Board) File No.: EB-2019-0012

Ladysmith Storage Pool

On June 13, 2019 the Board received a letter of comment for the above noted application from Mr. Gary Robbins of Robbins Farms. In that letter of comment Mr. Robbins indicated concerns that the existing lane way on the Ladysmith site has caused drainage issues and that additional development on the Ladysmith site could lead to further drainage issues. Mr. Robbins requested that assurances be given, and plans provided for how the water drainage issue will be addressed and mitigated.

On July 12, 2019 Enbridge Gas met with Mr. Robbins on the Ladysmith site. At that meeting Mr. Robbins showed Enbridge Gas his area of concern. The area of concern is a naturally occurring lower elevation spot located adjacent to the existing laneway which provides access to the Ladysmith site. Upon initial inspection of the land, it does not appear as though the drainage issue is caused by the Ladysmith project. However, in order to understand the cause of the drainage issue and to address Mr. Robbins' concern, Enbridge Gas has retained a drainage contractor to survey the area and determine potential solutions to mitigate the drainage issue.

Please contact me if you have any questions.

Yours truly,

(Original Signed)

Joel Denomy Technical Manager

Cc: Mr. Gary Robbins, Robbins Farms