

VIA EMAIL and RESS

July 6, 2021

Ms. Christine Long Registrar Ontario Energy Board 2300 Yonge Street, Suite 2700 Toronto, Ontario, M4P 1E4

Dear Ms. Long:

Re: Enbridge Gas Inc. ("Enbridge Gas")

Ontario Energy Board ("Board") File No.: EB-2018-0097

Bathurst Reinforcement Project ("Project")

On January 3, 2019, the Ontario Energy Board ("OEB"), in its Decision and Order for EB-2018-0097, granted Enbridge Gas Inc. ("Enbridge") leave to construct natural gas pipeline and ancillary facilities to meet current and future natural gas demand in the North York area of the City of Toronto. This project is referred to as the Bathurst Reinforcement Project ("the Project").

On May 25, 2021, Enbridge filed the Post-Construction Final Monitoring Report ("Final Report") for the Project with the OEB, however, there was one residual issue identified, in which Enbridge committed to providing a technical memorandum once resolved.

Enclosed please find the memorandum filed by Enbridge Gas in the above noted proceeding.

Please contact me if you have any questions.

Yours truly,

Alison Evans **Advisor Rates** Regulatory Application



Bathurst Reinforcement Project: Technical Memorandum EB-2018-0097

Company: Enbridge Gas Inc.



Table of Contents

Introduction	3
Residual Issues	3
Summary	3
Appendix A	4
Photo Log	4



Introduction

On January 3, 2019, the Ontario Energy Board ("OEB"), in its Decision and Order for EB-2018-0097, granted Enbridge Gas Inc. ("Enbridge") leave to construct natural gas pipeline and ancillary facilities to meet current and future natural gas demand in the North York area of the City of Toronto. This project is referred to as the Bathurst Reinforcement Project ("the Project").

On May 25, 2021, Enbridge filed the Post-Construction Final Monitoring Report ("Final Report") for the Project with the OEB, however, there was one residual issue identified, in which Enbridge committed to providing a technical memorandum once resolved.

Residual Issues

As documented in Photo 6 and Appendix D of the Final Report, repairs to the TTC bus stop were required and were scheduled for completion in mid-May 2021.

These repairs have been completed and photos are provided in Appendix A.

Summary

This technical memorandum has been prepared to document the closure of the outstanding residual issue as part of the Project.



Appendix A

PHOTO LOG





Photo 1: West Side of Bathurst St., South of Kenton Dr. (looking north). TTC bus stop pad prior to repair.



Photo 2: West Side of Bathurst St., South of Kenton Dr. (looking north west). TTC bus stop pad after repair.